

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1068,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

09/10/2020

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SGQ390B

Veh Model :- NISSAN LATIO

Estimate# :- CK421097

Claim # :-

ACC. Date :- 07/10/20

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
NET ITEMS :				
1.	REAR BOOT	1 PC	876.50	876.50
2.	REAR BOOT LOGO	1 PC	69.70	69.70
3.	REAR BOOT EMBLEM "LATIO"	1 PC	89.90	89.90
4.	REAR BOOT CHROME TOP	1 PC	256.10	256.10
5.	REAR BOOT CHROME LOWER	1 PC	190.70	190.70
6.	REAR BOOT RUBBER	1 PC	120.10	120.10
7.	REAR BOOT LOCK	1 PC	148.30	148.30
8.	REAR BOOT CATCH	1 PC	107.20	107.20
9.	REAR BOOT HINGES L+R	2 PC	86.40	172.80
10.	REAR LAMP L+R	2 PC RH-?	297.60	595.20
11.	REAR LAMP CLIPS	2 PC RH-?	9.40	18.80
12.	REAR LAMP PANEL L+R	2 PC	174.00	348.00
13.	REAR END PANEL	1 PC	577.80	577.80
14.	REAR END PANEL TRIM	1 PC	129.00	129.00
15.	REAR END PANEL TRIM CLIPS	6 PC	4.40	26.40
16.	REAR BUMPER	1 PC	582.40	582.40
17.	REAR BUMPER RETAINER	2 PC	63.60	127.20
18.	REAR BUMPER BRACKET	2 PC	79.30	158.60
19.	REAR BUMPER LOWER GARNISH	1 SET	414.20	414.20
20.	REAR BUMPER SPONGE	1 PC	57.00	57.00
21.	REAR BUMPER CLIPS	10 PC	4.40	44.00
22.	REAR FLOOR TOP COVER	1 PC	452.30	452.30
23.	REAR FLOOR PANEL (REPAIR)	1 PC		
24.	REAR FENDER L+R (REPAIR)	2 PC		
NET TOTAL S\$				5,562.20
10% DISCOUNT S\$				-556.22
				5,005.98
SPECIAL NET ITEMS :				
1.	REAR BUMPER SENSOR	1 PC	280.00	280.00
SPECIAL NET TOTAL S\$				280.00
LABOUR :				
TO CUT & WELD REAR END PANEL, TO REPAIR REAR FLOOR PANEL, REAR FENDER L+R, REAR CHASSIS MEMBER, TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS				
TO SPRAY AFFECTED AREAS				
TO REMOVE & REFOX LUGGAGE COMPARTMENT SIDE GARNISH, SIDE COVER, AND ATTACHMENT PARTS				
TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE				
TO RUST PROOF AFFECTED AREAS				

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

09/10/2020

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1 139251

Veh # :- SGQ390B

Veh Model :- NISSAN LATIO

Estimate# :- CK421097

Claim # :-

ACC. Date :- 07/10/20

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	LABOUR TOTAL S\$			1,930.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 7,215.98

GST @ 7 % 505.12

AMOUNT DUE S\$ 7,721.10

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Tanfer 92415441
'UP' 12/10/2020 Spr
Lump
Resurvey after repair.
Tanfer @ Khartoum
6-7 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: