

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20011000/R1GS3Q2

Date: 08/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700083508

Claimant
Vehicle No : SKP6913L **Insured Vehicle No :** SKD3341U

Date of Loss: 10/10/2020 Nature of Claim: TP Claim No: 7934873651SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP6913L		
Make & Model:	VOLKSWAGEN GOLF, 1.4 A7 TSI (A)	Engine No:	CXS215672
Reg. Date:	30/09/2014 (Man. Year: 2014)	Chassis No:	WVWZZZAUZFW026432
Colour:	Grey	Odometer:	73315 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,547.10	1,783.24	763.86	29.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	2,120.00	3,280.00	60.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,947.10	3,903.24	4,043.86	50.88
+ GST 7.00/7.00% (S\$)	556.30	273.23	283.07	50.88
Nett Amount (S\$)	8,503.40	4,176.47	4,326.93	50.88
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,328.47		

INSPECTION

Date of Assignment: 15/10/2020

Date Inspected: 15/10/2020 Inspected At: Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED REAR BUMPER	Deformed	1,165.55 FS	*1,165.55 FS
2	1		*SET SENSOR BRACKETS RH	Necessary	21.89 FS	*21.89 FS
3	1		*SENSOR BRACKET	Necessary	14.21 FS	*14.21 FS
4	1		*SENSOR BRACKET	Necessary	14.21 FS	*14.21 FS
5	1		*SENSOR BRACKET	Necessary	14.21 FS	*14.21 FS
6	1		*SENSOR BRACKET	Necessary	14.21 FS	*14.21 FS
7	1		*ATTACHMENT STRIP RR CTR BRACKET	Serviceable	64.97 FS	*- FS
8	1		*BUMPER REINFORCEMENT	Serviceable	619.61 FS	*- FS
9	4		*RIVET	Not Necessary	4.36 FS	*- FS
10	1		*GUIDE PIECE LHR TAILLIGHT BRACKET	Serviceable	37.46 FS	*- FS
11	1		*GUIDE PIECE RHR TAILLIGHT BRACKET	Serviceable	37.46 FS	*- FS
12	1		*NUMBER PLATE	Bent	80.00 FS	*80.00 FS
13	1		*REAR DIFFUSOR SATIN BLACK	Scratched	323.62 FS	*323.62 FS
14	1		*2K-PLASTIC ADHESIVE	Necessary	75.94 FS	*75.94 FS
15	1		*BONDING AGENT FOR PLASTIC	Necessary	59.40 FS	*59.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 2,547.10 1,783.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	LABOUR	New	2,520.00	840.00
3	SPRAY PAINTING	New	2,400.00	800.00
Gross Labour Cost (\$\$)			5,400.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >