



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20011004/Atd3q2

(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRESINGAPORE  
239924

Date : 09-11-2020



Code : AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |             |                |            |
|--------------|-------------|----------------|------------|
| Insured Veh. | SJF 4470A   | Veh. Inspected | SGT 4040U  |
| Policy No.   |             | Coverage (\$)  | 0.00       |
| Claim No.    | C10007532   | Excess (\$)    | 0.00       |
| Assign From  | IVY RATILLA | Assign Date    | 12/10/2020 |

### 2. Vehicle Particulars & Condition

|              |                   |              |            |
|--------------|-------------------|--------------|------------|
| Make & Model | MAZDA 3           | c.c          | 1496       |
| Engine No.   | HIDDEN            | Year of Reg. | 2015       |
| Chassis No.  | JM6BM42A8G0319964 | Colour       | BLUE       |
| Odometer     | 80566             | Steering     | IN ORDER   |
| Brakes       | IN ORDER          | Modification | SPORTS RIM |
| General      | GOOD              |              |            |

### 3. Conditions of Tyres

|                | Size       | Make | Balance |
|----------------|------------|------|---------|
| R/H Front Tyre | 205/60 R16 | TOYO | 6 mm    |
| L/H Front Tyre | 205/60 R16 | TOYO | 6 mm    |
| R/H Rear Tyre  | 205/60 R16 | TOYO | 6 mm    |
| L/H Rear Tyre  | 205/60 R16 | TOYO | 6 mm    |

### 4. Description of Damages

|  |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|--|

### 5. General Information

|                |  |                 |            |
|----------------|--|-----------------|------------|
| Accident Date  | 06/10/2020   | Inspection Date | 12/10/2020 |
| Survey held at | AUTOMOBILE HUB ENTERPRISE<br>1 KAKI BUKIT AVENUE 6<br>#02-11 AUTOBAY<br>SINGAPORE 417883 |                 |            |

### 5a. Remarks

|  |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 6 Working Days |
|-------------------------------------|----------------|