

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011006/T1QD3Q2

Date: 29/10/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMHCSN30706419011	
Claimant Vehicle No : SHB4822M	Insured Vehicle No : SME5612X	
Date of Loss: 09/10/2020	Nature of Claim: TP	Claim No: SNM20D203784C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB4822M	Engine No: D4FDEU483047
Make & Model: HYUNDAI I40, 1.7 D CRDi (A)	Chassis No: KMHLB41UMHU098355
Reg. Date: 18/01/2017 (Man. Year: 2016)	Odometer: 554820 km
Colour: Yellow	
Engine Capacity: 1685 cc	
Market Value/New Car Price: N/A	
Sum Insured (\$\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,968.11	3,838.11	130.00	3.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,180.00	780.00	39.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,928.11	5,018.11	910.00	15.35
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	5,928.11	4,000.00	1,928.11	32.52
+ GST 7.00/7.00% (\$\$)	414.97	280.00	134.97	32.53
Nett Amount (\$\$)	6,343.08	4,280.00	2,063.08	32.52

INSPECTION

Date of Assignment:	10/10/2020	
Date Inspected:	12/10/2020 Inspected At:	31 CORPORATION ROAD
		Repairer: Ding Automotive Pte Ltd (SIN MING)
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2020)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB4822M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	599.68 FL	*599.68 FL
2	1		*FRONT BUMPER RETAINER RH	Deformed	48.32 FL	*48.32 FL
3	1		*HEADLAMP RH	Cut	1,808.10 FL	*1,808.10 FL
4	1		*FRONT FENDER RH	Bent	659.60 FL	*659.60 FL
5	1		*FRONT FENDER INNER SHIELD RH	Deformed	185.12 FL	*185.12 FL
6	1		*FRONT WHEEL CAP RH	Cut	265.20 FL	*265.20 FL
7	1		*FRONT SUPPORT PANEL	Cracked	962.87 FL	*962.87 FL
8	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
9	1		*SET FRONT FENDER INNER SHIELD CLIP RH	Necessary	35.00 FS	*25.00 FS
10	1		*FRONT FENDER ADS STICKER RH	Necessary	150.00 FS	*100.00 FS
11	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
12	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,873.89	4,743.89
- List Item Discount on L Items 20.00/20.00% (\$\$)	905.78	905.78
Total Parts (\$\$)	3,968.11	3,838.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREA	New	900.00	500.00
2	RUST PROOFING	New	80.00	30.00
3	ADJUST HEADLAMP AIM & CHECK WIRING & CHECK LIGHTING SYSTEM	New	150.00	30.00
4	R&R RADIATOR & A/C CONDENSER & TURBO INTERCOOLER	New	180.00	120.00
5	VACUUM & TOP UP AIR COND GAS R-134A	New	150.00	100.00
6	RESPRAY FRONT BUMPER	New	250.00	200.00
7	RESPRAY FRONT FENDER RH	New	250.00	200.00
Gross Labour Cost (\$\$)			1,960.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >