

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 13 Oct 2020

**Preliminary Advice**

Insured Vehicle No	: SME5612X	Accident Date	: 09/10/2020
TP Vehicle No	: SHB4822M	Assignment Date	: 10/10/2020
Make	: HYUNDAI I40	Est. Duration of Repair	: 3
Date of Inspection	: 12/10/2020		
Inspection At	: DING AUTOMOTIVE PTE LTD (SIN MING) BLK 10 #01-20 SIN MING, IND EST SEC C SINGAPORE 575645		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,928.12
Revised Amount	:S\$	3,797.82
Check Items (Estimated)	:S\$	1,160.30
Total	:S\$	4,958.12

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :