

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20011013/R1VD3E2

Date: 10/11/2020

REFERENCE

Insured/Claimant:	HO KAN PING	Policy No:	2100428854
Date of Loss:	10/10/2020	Nature of Claim:	OD
		Claim No:	2042913549SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV4088A		
Make & Model:	CITROEN GRAND C4 PICASSO, 1.6 D e-HDi ETG6 Intensive (A)	Engine No:	10JBEX3056465
Reg. Date:	17/09/2015 (Man. Year: 2015)	Chassis No:	VF73A9HC8FJ637397
Colour:	Grey	Odometer:	91094 km
Engine Capacity:	1560 cc		
Market Value/New Car Price:	S\$52,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,694.80	5,708.00	2,986.80	34.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,805.00	3,525.00	1,280.00	26.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,499.80	9,233.00	4,266.80	31.61
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	13,199.80	8,933.00	4,266.80	32.32
+ GST 7.00/7.00% (S\$)	923.99	625.31	298.68	32.33
Nett Amount (S\$)	14,123.79	9,558.31	4,565.48	32.32

INSPECTION

Date of Assignment: 13/10/2020
Date Inspected: 13/10/2020 Inspected At:

Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)
209 PANDAN GARDENS
Singapore 609339

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*FRONT BUMPER	Torn	1,127.00 FL	*1,127.00 FL
3	1		*BUMPER BRACKET	Cracked	324.00 FL	*324.00 FL
4	1		*AIR DUCT RH	Cracked	111.00 FL	*111.00 FL
5	1		*BUMPER MOULDING RH	Cracked	142.00 FL	*142.00 FL
6	1		*GUARD GRILLE	Deformed	339.00 FL	*339.00 FL
7	1		*BADGE SUPPORT	Cracked	178.00 FL	*178.00 FL
8	1		*EMBLEM STRIPE	Cracked	289.00 FL	*289.00 FL
9	1		*FINISHER BUMPER	Cracked	244.00 FL	*244.00 FL
10	1		*SET BRACKET	Cracked	122.00 FL	*122.00 FL
11	1		*BUMPER MOULDING	Serviceable	293.00 FL	*- FL
12	1		*BRACKET SET LAT	Serviceable	122.00 FL	*- FL
13	1		*PLUG	Not Necessary	92.00 FL	*- FL
14	1		*SET ABSORBERS	Serviceable	90.00 FL	*- FL
15	1		*BUMPER BRACKET	Deformed	506.00 FL	*506.00 FL
16	1		*LOW FR PAN FIX	Necessary	157.00 FL	*157.00 FL
17	1		*FACE CROSSMEMBR SUP	Serviceable	256.00 FL	*- FL
18	1		*SET ABSORBERS	Serviceable	90.00 FL	*- FL
19	1		*AIR BULKHEAD LH	Serviceable	106.00 FL	*- FL
20	1		*AIR BULKHEAD RH	Serviceable	106.00 FL	*- FL
21	1		*AIR BULKHEAD	Serviceable	151.00 FL	*- FL
22	1		*FR MIN BPR FIX	Necessary	250.00 FL	*250.00 FL
23	1		*FRONT WING LH ASS	Repair	560.00 FL	*- FL
24	1		*ENGINE BONNET ASS	Bent	1,022.00 FL	*1,022.00 FL
25	1		*FRONT LIGHT LH	Serviceable	485.00 FL	*- FL
26	1		*FRONT LIGHT RH	Cracked	508.00 FL	*508.00 FL
27	1		*HEADLIGHT ASSY LH	Serviceable	705.00 FL	*- FL
28	1		*HEADLIGHT ASSY RH	Broken	705.00 FL	*705.00 FL
29	1		*FRONT WING RH ASS	Bent	560.00 FL	*560.00 FL
30	1		*FACE CROSSMEMBR INF ASS	Serviceable	80.00 FL	*- FL
31	1		*BUMPER DEFLECTOR	Cracked	484.00 FL	*484.00 FL
32	1		*DIST CHB BRAKCTET	Cracked	42.00 FL	*42.00 FL
33	1		*FRONT WING RH ASS	Repeated	560.00 FL	-

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,856.00	7,130.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,161.20	1,422.00
Total Parts (\$\$)	8,694.80	5,708.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRT BUMPER, BONNET, FRT SUPPORT & AFFECTED AREA. TO REPLACE ON BOTH FRT FENDER	New	2,750.00	1,750.00
2	TO REMOVE & INSTALL RADIATOR, AIRCON FOR FACILITATE REPAIR	New	180.00	0.00
3	TO TOP UP AIRCON GAS	New	80.00	0.00
4	CHECK CHASSIS ELECTRICAL & WIRING SYSTEM	New	50.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	225.00	225.00
6	PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER	New	1,520.00	1,520.00
Gross Labour Cost (S\$)			4,805.00	3,525.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >