

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG20011024/T1VD3E2

**Date:** 12/11/2020

#### REFERENCE

Insured/Claimant:	WAN KOK WENG	Policy No:	1900059259	
Date of Loss:	10/10/2020	Nature of Claim:	OD	Claim No: 1944865756SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMJ5909P</b>		
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGJH719820
Reg. Date:	13/03/2019 (Man. Year: 2018)	Chassis No:	KNAF3416MK5030341
Colour:	White	Odometer:	56262 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,112.00	5,590.00	5,522.00	49.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,220.00	2,640.00	1,580.00	37.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,332.00</b>	<b>8,230.00</b>	<b>7,102.00</b>	<b>46.32</b>
<b>- Excess (S\$)</b>	<b>3,300.00</b>	<b>3,300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>12,032.00</b>	<b>4,930.00</b>	<b>7,102.00</b>	<b>59.03</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>842.24</b>	<b>345.10</b>	<b>497.14</b>	<b>59.03</b>
<b>Nett Amount (S\$)</b>	<b>12,874.24</b>	<b>5,275.10</b>	<b>7,599.14</b>	<b>59.03</b>

#### INSPECTION

Date of Assignment: 13/10/2020

Date Inspected: 14/10/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 7.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CARRIER ASSY - FRONT END MODULE	Bent	675.00 FL	*675.00 FL
2	1		*BEAM COMPLETE - FR BUMPER	Bent	497.00 FL	*497.00 FL
3	1		*CONDENSER ASSY - COOLER	Bent	687.00 FL	*687.00 FL
4	1		*CONDENSER ASSY - COOLER	Not Necessary	687.00 FL	*- FL
5	1		*GUARD - AIR, RH	Not Necessary	28.00 FL	*- FL
6	1		*RADIATOR ASSY	Bent	646.00 FL	*646.00 FL
7	1		*BLOWER ASSY	Not Necessary	656.00 FL	*- FL
8	1		*PANEL - FENDER, LH	Repair	430.00 FL	*- FL
9	1		*INSULAOTOR - FENDER LH	Not Necessary	27.00 FL	*- FL
10	1		*LAMP ASSY - HEAD, LH	Cut	2,210.00 FL	*2,210.00 FL
11	1		*LAMP ASSY - HEAD, RH	Not Necessary	2,210.00 FL	*- FL
12	1		*BRACKET - FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
13	1		*BRACKET - FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
14	1		*STIFFENER - FR BPR LWR	Not Necessary	114.00 FL	*- FL
15	1		*ABSORBER - FRONT BUMPER ENERGY	Cracked	84.00 FL	*84.00 FL
16	1		*AIR DUCT - FR BUMPER, LH	Not Necessary	14.00 FL	*- FL
17	1		*LAMP ASSY - SIDE REPEATER, LH	Not Necessary	143.00 FL	*- FL
18	1		*MOULDING - FRONT BUMPER, LH	Cracked	216.00 FL	*216.00 FL
19	1		*LAMP ASSY - FRONT FOG, LH	Not Necessary	303.00 FL	*- FL
20	2		*RETAINER - BUMPER SIDE MTG	Not Necessary	2.00 FL	*- FL
21	1		*GARNISH - RADIATOR GRILLE	Cracked	38.00 FL	*38.00 FL
22	1		*GRILLE ASSY - RADIATOR	Cracked	328.00 FL	*328.00 FL
23	1		*COVER - FR BUMPER	Deformed	633.00 FL	*633.00 FL
24	4		*GRILLE - FRONT BUMPER	Cracked (1pc Only)	1,940.00 FL	*485.00 FL
25	1		*COVER - FR BUMPER, FOG LAMP, LH	Cut	15.00 FL	*15.00 FL
26	1		*WIRING ASSY - BUMPER EXTENSION	Not Working	207.00 FL	*207.00 FL
27	1		*ULTRASONIC SENSOR ASSY - P.A.S	Not Necessary	163.00 FL	*- FL
28	1		*ULTRASONIC SENSOR ASSY - P.A.S	Not Necessary	163.00 FL	*- FL
29	1		*ULTRASONIC SENSOR ASSY - P.A.S	Not Necessary	163.00 FL	*- FL
30	1		*ULTRASONIC SENSOR ASSY - P.A.S	Not Necessary	163.00 FL	*- FL
31	1		*ORNAMENT - KIA NO.115	Necessary	32.00 FL	*32.00 FL
32	1		*BODY SEALANT	Not Necessary	80.00 FS	*- FS
33	1		*FRONT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
34	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
35	1		*GUARD-AIR,LH	Cracked	28.00 FL	*28.00 FL
36	1		*BUZZER ASSY-PIEZO	Cracked	68.00 FL	*68.00 FL
37	1		*DUCT-EXTENSION	Deformed	5.00 FL	*5.00 FL
38	1		*COOLANT (4L)	Necessary	26.00 FL	*26.00 FL
39	10		*CLIPS	Necessary	20.00 FL	*20.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>13,845.00</b>	<b>6,970.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	2,733.00	1,380.00
<b>Total Parts (\$)</b>	<b>11,112.00</b>	<b>5,590.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW ACCIDENT DAMAGED ON FRONT SUPPORT PANEL, FRONT BUMPER, LH FRONT FENDER, REPAIR FRONT BONNET.	New	1,600.00	800.00
2	REMOVE AND INSTALL PARKING ASSIST.	New	60.00	60.00
3	REMOVE AND INSTALL RADIATOR AND A/CON CONDNER.ER.	New	100.00	100.00
4	TOP UP A/CON GAS AND CHECK A/CON SYSTEM.	New	80.00	80.00
5	PAINT WORK SPRAY FRONT BUMPER, LH FRONT FENDER, RH FRONT FENDER, BONNET AND AFFECTED PORTION.	New	1,750.00	1,050.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.	New	30.00	30.00
7	PERFORM RUST PREVENTION.	New	80.00	0.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.	New	120.00	120.00
9	REPLACE FRONT SUPPORT PANEL.	New	400.00	400.00
			<b>Gross Labour Cost (S\$)</b>	<b>4,220.00</b>
				<b>2,640.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >