

CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Table with 2 columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for a KIA CERATO 1.6 A SR SX G335.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: LAX0000, Credit, 12/10/2020/ 09:31, QUD, 247 / DonBong, 22517


Main table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various repair items like 'RENEW ACCIDENT DAMAGED ON FRONT SUPPORT PANEL' and 'PAINT WORK SPRAY FRONT BUMPER'.

Estimate

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation

Confirm & accepted by
Acknowledged by Repairer
Signature:
Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCY08852/WAN KOK WENG Reg No/Reg Date SMJ5909P*KC17/ 13/03/201 Date In/Mileage / 0 Chassis No KNAF3416MK5030341 Engine No G4FGJH719820 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	12/10/2020/ 09:31	QUD	247 / DonBong	22517

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M PANEL-FENDER,LH	1.00	430.00	20.00	344.00
M INSULATOR-FENDER LH	1.00	27.00	20.00	21.60
M LAMP ASSY-HEAD,LH	1.00	2210.00	20.00	1768.00
M LAMP ASSY-HEAD,RH	1.00	2210.00	20.00	1768.00
M BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	20.00	17.60
M BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	20.00	17.60
M STIFFNER-FR BPR LWR	1.00	114.00	20.00	91.20
M ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	20.00	67.20
M AIR DUCT-FR BUMPER,LH	1.00	14.00	20.00	11.20
M LAMP ASSY-SIDE REPEATER,LH	1.00	143.00	20.00	114.40
M MOULDING-FRONT BUMPER,LH	1.00	216.00	20.00	172.80
M LAMP ASSY-FRONT FOG,LH	1.00	303.00	20.00	242.40
M RETAINER-BUMPER SIDE MTG	2.00	1.00	20.00	1.60
M GARNISH-RADIATOR GRILLE	1.00	38.00	20.00	30.40
M GRILLE ASSY-RADIATOR	1.00	328.00	20.00	262.40
M COVER-FR BUMPER	1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER	1.00	485.00	20.00	388.00
M COVER-FR BUMPER FOG LAMP,LH	1.00	15.00	20.00	12.00
M WIRING ASSY-BUMPER EXTENSION	1.00	207.00	20.00	165.60
M ULTRASONIC SENSOR ASSY-P.A.S	1.00	163.00	20.00	130.40
M ULTRASONIC SENSOR ASSY-P.A.S	1.00	163.00	20.00	130.40
M ULTRASONIC SENSOR ASSY-P.A.S	1.00	163.00	20.00	130.40
M ULTRASONIC SENSOR ASSY-P.A.S	1.00	163.00	20.00	130.40
M ORNAMENT-KIA NO.115	1.00	163.00	20.00	130.40
	1.00	32.00	20.00	25.60

Estimate

SURVEYOR NAME: Taufik 97495749

SURVEYOR SIGNATURE: [Signature]

DATE: 14/10/2020 10:30

REMARKS: Not Authorise Revert.
Resolving before paint to Taufik@khauto.com

Confirm & accepted by

04 days

7% GST on	14814.40	1037.01
Nett	14,814.40	
Total Payable		15,851.41

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made by cheque. You must also agree to pay full amount for renewal of the windscreen in the event of a repair requiring the replacement of the rubber seal or other repair requiring the replacement of the windscreen.