

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

INV No. AC2007539

INV Date 11/11/2020

Reference CC3/CTI20011025/Eda3q2

Code CT

### **PROFESSIONAL SERVICE FEE**

Vehicle No. SHC 6231A

Insured Veh. SMF 5992T

Claim No. SNM20D203798

Policy No. DMPCSNW00114172000

Accident Date 08/10/2020

Inspection Date 12/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile				
CHIN	CHINA TAIPING INSURANCE (S) PTE LTD Ref: CC3/CTI20011025/Eda3q2				
	SON ROAD #16-0 NGLEAF TOWER	00 SINGAPORE 079909	Date: 11-11-2020 Code: CTI		
1.		Policy Particulars	- THIRD PARTY CLAIM		
	Insured Veh.	SMF 5992T	Veh. Inspected	SHC 6231A	
	Policy No.	DMPCSNW00114172000	Coverage (\$)	0.00	
	Claim No.	SNM20D203798	Excess (\$)	0.00	
	Assign From	Adeline Chng	Assign Date	12/10/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	KIA OPTIMA	c.c	1685	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	KNAGM414MF5542433	Colour	SILVER	
	Odometer	481342	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3.		Condition	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	185/55 R15	MICHELIN	5 mm	
	L/H Front Tyre	185/55 R15	MICHELIN	5 mm	
	R/H Rear Tyre	185/55 R15	MICHELIN	5 mm	
	L/H Rear Tyre	185/55 R15	MICHELIN	5 mm	
4.		•	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR PORTION.		
	DAMAGES SEE D	ETAILS.			
5.		General	Information		
	Accident Date	08/10/2020	Inspection Date	12/10/2020	
	Survey held at	PREMIER AUTOMOTIVE SERVI	ICES PTE LTD		
	23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443				
5a.		Re	emarks		
	A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
5b.	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. <b>b.</b> Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Days		
	I				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6231A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	END PANEL	TO REPAIR SEE LABOUR	250.00	-
1	END PANEL INNER GARNISH	NOT NECESSARY	74.00	-
1	REAR BUMPER	DENTED	696.00	696.00
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	BROKEN	58.00	58.00
1	REAR BUMPER INNER SPONGE	NOT NECESSARY	114.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	607.00	-
2	REAR BUMPER STAY O/S & N/S	NOT NECESSARY	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	NOT NECESSARY	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	NOT NECESSARY	36.00	-
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	NOT NECESSARY	92.00	-
	LESS 10% DISCOUNT		-227.70	-96.00
			2,049.30	864.00
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	30.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET BOOTLID STICKERS (SN)	NOT NECESSARY	100.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	80.00	60.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			588.00	310.00
	<u>LABOUR</u>			
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE/REFIT THE INNER GARNISHES,INNER LININGS,INNER TRIMS,CUSHION SEAT,CARPET,ETC TO FACILITATE REPAIRS.		180.00	20.00

Report Ref No. CC3/CTI20011025/Eda3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.TO HEAT/WELD,CUT-OFF THE THE END PANEL,INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE THE SAME.		800.00	300.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID LOWER GARNISH,REAR BUMPER,END PANEL,BOOT LID.		800.00	300.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	20.00
			2,050.00	670.00
	GRAND TOTAL		4,687.30	1,844.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		1,500.00

Report Ref No. CC3/CTI20011025/Eda3q2

la.

**CHEN TSUE YEE** 

**Automotive Assessor** 

Amonto

**HO LEONG CHUAN** 

**Automotive Assessor** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SHC 6231A

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SHC 6231A









