

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011026/DGA3Q2

Date: 02/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900258675

**Claimant**  
**Vehicle No :** GBJ5602D **Insured Vehicle No :** GBK784P

Date of Loss: 04/10/2020 Nature of Claim: TP Claim No: 4278830857SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |               |
|-----------------------------|-----------------------------------|-------------|---------------|
| Reg No:                     | <b>GBJ5602D</b>                   |             |               |
| Make & Model:               | TOYOTA HIACE, 2.8 D (A)           | Engine No:  | 1GD8413238    |
| Reg. Date:                  | 07/06/2019 (Man. Year: 2019)      | Chassis No: | GDH2011023492 |
| Colour:                     | Silver                            | Odometer:   | 76661 km      |
| Engine Capacity:            | 2754 cc                           |             |               |
| Market Value/New Car Price: | N/A                               |             |               |
| Sum Insured (\$):           | <b>Market Value/New Car Price</b> |             |               |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 195 R15          | Rear Tyre Size:  | 195 R15          |
| Front Left Side:  | Bridgestone 5 mm | Rear Left Side:  | Bridgestone 5 mm |
| Front Right Side: | Bridgestone 5 mm | Rear Right Side: | Bridgestone 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                   | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-----------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                   | 14,924.55         | 5,073.67          | 9,850.88          | 66.00         |
| Miscellaneous Items                     | 0.00              | 0.00              | 0.00              |               |
| Labour                                  | 5,580.00          | 1,240.00          | 4,340.00          | 77.78         |
| Paintwork Labour                        | 0.00              | 0.00              | 0.00              |               |
| Towing                                  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$)</b>      | <b>20,504.55</b>  | <b>6,313.67</b>   | <b>14,190.88</b>  | <b>69.21</b>  |
| <b>Approved Total (Overridden) (\$)</b> |                   | <b>5,050.00</b>   |                   |               |
| <b>(\$)</b>                             | 20,504.55         | 5,050.00          | 15,454.55         | 75.37         |
| <b>+ GST 7.00/7.00% (\$)</b>            | 1,435.32          | 353.50            | 1,081.82          | 75.37         |
| <b>Nett Amount (\$)</b>                 | <b>21,939.87</b>  | <b>5,403.50</b>   | <b>16,536.37</b>  | <b>75.37</b>  |
| <b>Global Sum Settlement (\$)</b>       |                   | <b>0.00</b>       |                   |               |

### INSPECTION

Date of Assignment: 13/10/2020

Date Inspected: 14/10/2020 Inspected At:

 JWG International Pte Ltd (HQ)  
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08  
 AMK AutoPoint  
 Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                               | Condition                   | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------------|-----------------------------|-------------|--------------|
| 1   | 1   |          | *FRONT BONNET                             | Dented                      | 956.62 FL   | *825.50 FL   |
| 2   | 1   |          | *FRONT BONNET TOYOTA LOGO                 | Necessary                   | 66.15 FL    | *66.15 FL    |
| 3   | 2   |          | *FRONT BONNET HINGE LH & RH               | Not Necessary               | 97.70 FL    | *- FL        |
| 4   | 1   |          | *FRONT BONNET INNER LOCK                  | Not Necessary               | 182.90 FL   | *- FL        |
| 5   | 1   |          | *FRONT BONNET INNER LOCK CABLE            | Not Necessary               | 47.80 FL    | *- FL        |
| 6   | 2   |          | *FRONT BONNET INNER RUBBER SEAL           | Not Necessary               | 98.40 FL    | *- FL        |
| 7   | 1   |          | *SET FRONT BONNET INNER RUBBER SEAL CLIPS | Not Necessary               | 25.00 FL    | *- FL        |
| 8   | 1   |          | *FRONT UPPER GRILLE                       | Cut                         | 388.20 FL   | *221.70 FL   |
| 9   | 1   |          | *FRONT CENTRE GRILLE                      | Cut                         | 313.60 FL   | *313.60 FL   |
| 10  | 1   |          | *FRONT CENTRE GRILLE RADAR SENSOR ASSY    | Damaged                     | 1,299.10 FL | *1,299.10 FL |
| 11  | 1   |          | *FRONT LOWER GRILLE                       | Not Necessary               | 274.60 FL   | *- FL        |
| 12  | 1   |          | *SET FRONT GRILLE CLIPS                   | Necessary                   | 35.00 FL    | *35.00 FL    |
| 13  | 1   |          | *FRONT SUPPORT PANEL ASSY                 | Repair                      | 383.00 FL   | *- FL        |
| 14  | 1   |          | *FRONT BRACE PANEL                        | Not Necessary               | 86.70 FL    | *- FL        |
| 15  | 1   |          | *FRONT INTERCOOLER                        | Not Necessary               | 1,558.19 FL | *- FL        |
| 16  | 1   |          | *FRONT HEADLAMP LH& RH                    | O/S Cut / N/S Not Necessary | 5,413.60 FL | *2,584.30 FL |
| 17  | 1   |          | *FRONT RADIATOR                           | Not Necessary               | 2,268.20 FL | *- FL        |
| 18  | 1   |          | *FRONT RADIATOR TANK                      | Not Necessary               | 399.20 FL   | *- FL        |
| 19  | 1   |          | *FRONT AIR-CON CONDENSOR                  | Not Necessary               | 1,416.00 FL | *- FL        |
| 20  | 1   |          | *FRONT FAN MOTOR                          | Not Necessary               | 1,409.10 FL | *- FL        |
| 21  | 1   |          | *FRONT FAN MOTOR COWLING ASSY             | Not Necessary               | 366.38 FL   | *- FL        |
| 22  | 1   |          | *FRONT BUMPER                             | Cut                         | 548.20 FL   | *548.20 FL   |
| 23  | 1   |          | *SET FRONT BUMPER CLIPS                   | Necessary                   | 35.00 FL    | *35.00 FL    |
| 24  | 2   |          | *FRONT BUMPER SIDE RETAINER               | Not Necessary               | 57.40 FL    | *- FL        |
| 25  | 1   |          | *FRONT LH FENDER                          | Not Necessary               | 175.80 FL   | *- FL        |
| 26  | 1   |          | *FRONT LH FENDER MIRROR                   | Not Necessary               | 230.90 FL   | *- FL        |
| 27  | 1   |          | *RADIATOR COOLANT                         | Not Necessary               | 80.00 FS    | *- FS        |
| 28  | 1   |          | *FRONT SUPPORT PANEL SEALANTS             | Not Necessary               | 80.00 FS    | *- FS        |
| 29  | 1   |          | *TO DESIGN & PASTE FRONT COMPANY STICKER  | Not Necessary               | 300.00 FS   | *- FS        |
| 30  | 1   |          | *FRONT NO.PLATE & HOLDER                  | Cut / Bent                  | 80.00 FS    | *45.00 FS    |
| 31  | 1   |          | *FRONT GRILLE BASE                        | Mtg Cracked                 | 419.24 FL   | *419.24 FL   |
| 32  | 1   |          | *FRONT REINFORCEMENT BAR LOWER            | Bent                        | 627.42 FL   | *357.10 FL   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>19,719.40</b> | <b>6,749.89</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 4,794.85         | 1,676.22        |
| <b>Total Parts (\$\$)</b>                                  | <b>14,924.55</b> | <b>5,073.67</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                         | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                                                                     |          |                 |                 |
| 1                               | TO CHARGE & DISCHARGE AIR-CON GAS                                                   | New      | 100.00          | 0.00            |
| 2                               | TO REMOVE & REFIT FRONT AIR-CON CONDENSOR & RADIATOR & TO CONDUCT PRESSURE TEST     | New      | 400.00          | 0.00            |
| 3                               | TO REMOVE DAMAGE FRONT INTERCOOLER & CONDUCT TURBO PRESSURE TEST                    | New      | 300.00          | 0.00            |
| 4                               | TO REPLACE DAMAGED FRONT RADAR SENSOR ,DIAGNOSE & RESET TO RECTORY DEFAULT SETTINGS | New      | 500.00          | 180.00          |
| 5                               | TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS                             | New      | 1,800.00        | 600.00          |
| 6                               | TO RESPRAY NEW PAINTWORK ALL DAMAGED AREAS                                          | New      | 1,800.00        | 400.00          |
| 7                               | TO COMPUTERIZED REFOCUS FRONT HEADLAMP BEAM                                         | New      | 120.00          | 30.00           |
| 8                               | TO CHECK & REFIX ALL ELECTRICAL WIRINGS                                             | New      | 280.00          | 0.00            |
| 9                               | TO APPLY ANTI-RUST COATINGS ON ALL AFFECTED AREAS                                   | New      | 280.00          | 30.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                     |          | <b>5,580.00</b> | <b>1,240.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >