

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SGG6235E [YOUR INSURED] & SGX6309L [OUR CLIENT]
ON 02/10/2020.

ESTIMATED REPAIR COSTS FOR SGX6309L

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	FRONT DOOR R/H <i>tan</i>	\$ 859.55	X
1PC	ROCKER PANEL R/H <i>monitory broken H/L</i>	\$ 450.75	X
1PC	FRONT WHEEL BEARING R/H <i>Don</i>	\$ 346.05	✓
1PC	FRONT WHEEL BEARING HUB R/H <i>H/L</i>	\$ 423.55	X
1PC	FRONT KNUCKLE ARM R/H <i>distorted</i>	\$ 496.00	✓
1PC	FRONT LOWER ARM R/H <i>distorted</i>	\$ 380.10	✓
1PC	FRONT ABSORBER R/H <i>replaced</i>	\$ 427.15	X
1PC	TIE ROD R/H <i>H/L</i>	\$ 185.80	X
1PC	TIE ROD END R/H <i>H/L</i>	\$ 158.65	X
1PC	STABALIZER BAR R/H <i>H/L</i>	\$ 346.05	X
1PC	STABALIZER LINK R/H <i>H/L</i>	\$ 110.45	X
1PC	FRONT FENDER INNER SHIELD <i>turn</i>	<i>78.40</i> \$ 198.25	✓
✓			

1676.35

1424.89

PARTS SUM: \$ 4,184.10
PARTS LESS 15%: \$ 836.82
PARTS TOTAL: \$ 3,347.28

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY FRONT BUMPER <i>crack</i>	3330.00	1000/-	\$ 1,800.00	✓
*	TO SUPPLY FRONT FENDER R/H <i>crack</i>		800/-	\$ 1,800.00	✓
*	TO SUPPLY SIDE SKIRT R/H <i>monitory crack / broken</i>		600/-	\$ 1,200.00	✓
*	TO SUPPLY SIDE MIRROR ASSY R/H <i>crack repair</i>			\$ 1,000.00	✓
*	TO SUPPLY FRONT BUMPER FOG LAMP R/H <i>H/L</i>			\$ 80.00	X
*	TO SUPPLY FRONT BUMPER CLIPS <i>H/L</i>			\$ 50.00	X
*	TO SUPPLY SIDE SKIRT CLIPS <i>H/L</i>			\$ 80.00	X
*	TO SUPPLY HEAD LAMP R/H <i>monitory crack (original)</i>	375.80 (last)		\$ 1,800.00	✓
*	TO SUPPLY HEAD LAMP PROTECTIVE FILM <i>Nec</i>			\$ 300.00	30/-
*	TO SUPPLY 1PC RIM <i>distorted / cut</i>			\$ 1,800.00	450/-
X	TO SUPPLY COIL OVER (COHLING) <i>distorted</i>		450.00	\$ 1,800.00	✓

* TO SUPPLY 1PC TYRE <i>4w</i>	\$ 300.00 <i>X</i>
* TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00 <i>4w</i>
* TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 1,600.00 <i>700/-</i>
* TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 1,400.00 <i>800/-</i>
* TO TUFF COAT DAMAGED AREAS	\$ 300.00 <i>4w</i>
* TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	\$ 200.00 <i>4w</i>
* TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 250.00 <i>150/-</i>
* TO CONDUCT WHEEL ALIGNMENT TEST	<i>1740.00</i> \$ 100.00 <i>60/-</i>
* TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00 <i>30/-</i>
* TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00 <i>4w</i>

LABOUR & S/N TOTAL: \$ 14,860.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 18,207.28

12/10/2020 @ 1600hrs

Not Author

L/Smm

6 days.

[Signature]

Lkk Auto

[Signature]

Check Part prices.

6494.89

L/S 5100/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: