

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20011034/GVD3E2
Date: 16/10/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700003821
Claimant Vehicle No :	SJM2959J	Insured Vehicle No :	SLN5631E
Date of Loss:	09/10/2020	Nature of Claim:	TP
		Claim No:	3470817795SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM2959J		
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Engine No:	G4FC8U565312
Reg. Date:	27/12/2008 (Man. Year: 2008)	Chassis No:	KMH DU41BR9U647362
Colour:	Grey	Odometer:	268528 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	12/10/2020	
Date Inspected:	12/10/2020 Inspected At:	Em Solution Pte Ltd (160 Sin Ming) (HQ) 160 Sin Ming Drive, #03-19 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER BRACKET	Bent	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Distorted	0.00 F	*- F
6	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
7	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
8	1		*REAR END PANEL	Buckled	0.00 F	*- F
9	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
11	1		*BOOTLID	Buckled	0.00 F	*- F
12	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*BOOTLID LAMP RH	Cracked	0.00 F	*- F
14	1		*BOOTLID LOCK	Bent	0.00 F	*- F
15	1		*BOOTLID RUBBER	Twisted	0.00 F	*- F
16	1		*BOOTLID TRIM	Torn	0.00 F	*- F
17	1		*SPARE TYRE BOARD	Broken	0.00 F	*- F
18	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
19	1		*TRIANGLE BREAKDOWN SIGN BOX	Cracked	0.00 F	*- F
20	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
21	1		*REAR RH FENDER	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >