

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011035/GS3Q2

Date: 17/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100336768

Claimant
Vehicle No : GBH464D **Insured Vehicle No :** SJF9980L

Date of Loss: 10/10/2020 Nature of Claim: TP Claim No: 1516470013SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH464D		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30028945N
Reg. Date:	28/12/2017 (Man. Year: 2017)	Chassis No:	JN1SC2F24Z0860982
Colour:	Silver	Odometer:	44117 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,628.94	1,083.74	2,545.20	70.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	890.00	1,160.00	56.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,678.94	1,973.74	3,705.20	65.24
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	5,678.94	1,600.00	4,078.94	71.83
+ GST 7.00/7.00% (S\$)	397.53	112.00	285.53	71.83
Nett Amount (S\$)	6,076.47	1,712.00	4,364.47	71.83
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,894.00		

INSPECTION

Date of Assignment: 13/10/2020

Date Inspected: 03/11/2020 Inspected At:

Efficient Motor & Engineering Works
Pte Ltd (HQ)
56 Loyang Way #06-07, Loyang
Enterprise Building
Singapore 508775

Estimated Period of Repair: 3.0 days

Adjuster: ACCUSER4

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,399.70 FL	*- FL
2	1		*SIDE GATE LOCK	Not Necessary	490.00 FL	*- FL
3	1		*TAIL LAMP LH/RH	N/S Broken	497.20 FL	*248.60 FL
4	3		*TAIL DOOR HINGE	Not Necessary	111.30 FL	*- FL
5	1		*REAR NUMBER PLATE LIGHT	Not Necessary	78.40 FL	*- FL
6	1		*NISSAN STICKER	Necessary	100.00 FS	*80.00 FS
7	1		*TAIL LAMP BRACKET	N/S Bent	100.00 FS	*40.00 FS
8	1		*PAN PACIFIC METAL PLATE	Necessary	80.00 FS	*50.00 FS
9	1		*REVERSE SENSOR	Broken	200.00 FS	*200.00 FS
10	1		*REAR NO .PLATE	Bent	40.00 FS	*30.00 FS
11	1		*REAR NO .PLATE BRACKET	Not Necessary	30.00 FS	*- FS
12	1		*13 PAX STICKER	Necessary	30.00 FS	*30.00 FS
13	1		*70KM/H STICKER	Necessary	30.00 FS	*30.00 FS
14	2		*SPARE TYRE	Not Necessary	200.00 FS	*- FS
15	1		*REAR STEP BAR	Bent	500.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,886.60	1,108.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	257.66	24.86
Total Parts (\$\$)	3,628.94	1,083.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT & ALIGN REAR PORTION ,REMOVE & REPLACE DAMAGED PARTS	New	1,000.00	400.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	100.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	50.00	30.00
4	TO REMOVE AND REPLACE REVERSE SENSOR	New	100.00	30.00
5	TO SPRAY PAINTING FOR REAR PORTION & AFFECTED AREAS	New	800.00	400.00
Gross Labour Cost (\$\$)			2,050.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >