

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20011036/AVD3Q2**Date:** 15/03/2021**REFERENCE**

Insured/Claimant: NG ZI HAO Policy No: 1700079236-02  
Date of Loss: 08/10/2020 Nature of Claim: OD Claim No: 1331142218SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLU5949C**  
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN047470  
Reg. Date: 07/12/2017 (Man. Year: 2017) Chassis No: WAUZZZF45JA036156  
Colour: Black Odometer: 38136 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$100,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	22,271.00	12,696.00	9,575.00	42.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,402.00	5,132.00	1,270.00	19.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>28,673.00</b>	<b>17,828.00</b>	<b>10,845.00</b>	<b>37.82</b>
<b>- Excess (S\$)</b>	800.00	800.00	0.00	0.00
<b>(S\$)</b>	27,873.00	17,028.00	10,845.00	38.91
<b>+ GST 7.00/7.00% (S\$)</b>	1,951.11	1,191.96	759.15	38.91
<b>Nett Amount (S\$)</b>	<b>29,824.11</b>	<b>18,219.96</b>	<b>11,604.15</b>	<b>38.91</b>

**INSPECTION**

Date of Assignment: 13/10/2020

Date Inspected: 12/10/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,111.00 FS	*1,688.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	282.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	194.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	208.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Deformed	62.00 FS	*49.52 FS
7	1		*RADIATOR GRILLE	Not Necessary	1,139.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	134.00 FS	*106.80 FS
9	1		*FRONT BUMPER CENTRE	Not Necessary	795.00 FS	*- FS
10	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	37.00 FS	*29.52 FS
11	1		*FRONT BUMPER COVER	Not Necessary	126.00 FS	*- FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	123.00 FS	*- FS
13	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
14	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
15	1		*LOCK CARRIER BRACKET	Not Necessary	136.00 FS	*- FS
16	2		*LOCK CARRIER BRACKET SUPPORT - LH / RH	Not Necessary	56.00 FS	*- FS
17	1		*HORN - RH LOW TORN	Not Necessary	124.00 FS	*- FS
18	1		*SPRING SHACKLE - RH	Not Necessary	29.00 FS	*- FS
19	1		*FRONT FENDER - RH	Distorted	758.00 FS	*606.00 FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	200.00 FS	*- FS
21	1		*FRONT FENDER CLOSING ELEMENT - RH	Bent	49.00 FS	*39.20 FS
22	1		*FRONT FENDER BRACKET - RH	Bent	35.00 FS	*27.60 FS
23	1		*DEFORMATION ELEMENT BRACKET - RH	Not Necessary	49.00 FS	*- FS
24	1		*FRONT FENDER INNER REAR BRACKET	Not Necessary	31.00 FS	*- FS
25	1		*FRONT FENDER BRACE - RH	Bent	117.00 FS	*93.60 FS
26	1		*WHEEL HOUSING LINER - RH	Deformed	239.00 FS	*190.80 FS
27	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
28	1		*WHEEL SPOILER	Torn	73.00 FS	*57.76 FS
29	1		*WHEEL SPOILER TRIM - RH	Not Necessary	36.00 FS	*- FS
30	1		*SONE CHIP GUARD - RH	Necessary	50.00 FS	*39.92 FS
31	1		*TOP FENDER LEDGE COVER - INNER	Deformed	31.00 FS	*24.40 FS
32	1		*TOP FENDER LEDGE COVER - OUTER	Deformed	23.00 FS	*17.68 FS
33	1		*BONNET	Dented	2,763.00 FS	*2,210.40 FS
34	1		*BONNET ATTACHMENT PARTS	Not Necessary	121.00 FS	*- FS
35	1		*BONNET IMPACT PROTECTION - CENTRE	Necessary	27.00 FS	*21.52 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*BONNET IMPACT PROTECTION - RH	Necessary	27.00 FS	*21.52 FS
37	1		*BONNET IMPACT PROTECTION - LH	Necessary	28.00 FS	*21.84 FS
38	1		*LED HEADLIGHT - RH	Cracked	7,693.00 FS	*6,154.40 FS
39	1		*MAIN LIGHT ELECTRONIC POWER MODULE	Not Necessary	739.00 FS	*- FS
40	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	742.00 FS	*- FS
41	1		*LIFT CYLINDER - RH	Not Necessary	208.00 FS	*- FS
42	1		*EXERRIOR MIRROR MOUNTING - RH	Cut	886.00 FS	*708.80 FS
43	1		*MIRROR CAP - RH	Repair	261.00 FS	*- FS
44	1		*WINDOW SLOT SEAL - RH	Not Necessary	303.00 FS	*- FS
45	1		*FRONT ALUMINIUM RIM - RH	Cut	684.00 FS	*547.20 FS
46	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
47	1		*SUNDRIES	Necessary	300.00 FS	*38.72 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (\$\$)</b>					<b>22,271.00</b>	<b>12,696.00</b>

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATUE SENSOR AND HEADLIGHT WASHER ASSY.	New	280.00	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	New	350.00	250.00
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY.	New	350.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	2,000.00	1,500.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR AND RHS WING MIRROR COVER.	New	2,950.00	2,350.00
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
<b>Gross Labour Cost (\$)</b>			<b>6,402.00</b>	<b>5,132.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**