

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1380K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	IONIQVC COVER-RR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	IONIQV4 CAP ASSY-WHEEL HU	CUT	346.40	346.40
	LESS 20% DISCOUNT		-161.16	-69.28
			644.64	277.12
<u>NETT ITEMS</u>				
1	APP LOGO REAR DOOR L/R CT (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-	-8.00
			80.00	72.00
<u>SPECIAL NETT ITEMS</u>				
10	IONIQVC PROTECTOR MAT (SN)	NOT NECESSARY	500.00	-
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR FENDER ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
1	REAR DOOR ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
			850.00	350.00
<u>LABOUR</u>				
	PANEL BEATING (REPAIR REAR FENDER LH). INCLUSIVE OF THE REPAIR OF IONIQVC COVER-RR BUMPER.		700.00	320.00
	SPRAYPAINT ON AFFECTED AREA.		650.00	600.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	50.00	-
	REMOVE / REFIX REVERSE SENSOR.	NOT NECESSARY	80.00	-
	ADJUST REAR WHEEL ALIGNMENT.		80.00	60.00
			-	-
			-	-
			1,560.00	980.00
GRAND TOTAL			3,134.64	1,679.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,350.00

Report Ref No. NS/INC20011037/Etd3e2



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.