

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20011038/T1TD3E2

Date: 11/11/2020

REFERENCE

Insured/Claimant:	CHEE CHIN KHIAM	Policy No:	1900106342	
Date of Loss:	12/10/2020	Nature of Claim:	OD	Claim No: 1469643912SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM3851T			
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)		Engine No:	3A92UHT5876
Reg. Date:	27/06/2019 (Man. Year: 2019)		Chassis No:	MMBSTA13AKH002145
Colour:	Red		Odometer:	10311 km
Engine Capacity:	1193 cc			
Market Value/New Car Price:	S\$55,000.00			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,967.70	3,218.59	3,749.11	53.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,990.00	3,080.00	2,910.00	48.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,957.70	6,298.59	6,659.11	51.39
- Excess (\$\$)	300.00	300.00	0.00	0.00
(\$\$)	12,657.70	5,998.59	6,659.11	52.61
+ GST 7.00/7.00% (\$\$)	886.04	419.90	466.14	52.61
Nett Amount (\$\$)	13,543.74	6,418.49	7,125.25	52.61

INSPECTION

Date of Assignment: 13/10/2020
Date Inspected: 13/10/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY, FR END	Not Necessary	1,055.00 FL	*- FL
2	1		*PANEL, HEADLAMP SUPPORT, UPR	Not Necessary	65.00 FL	*- FL
3	1		*CONDENSER ASSY, A/C REFRIGE	Not Necessary	758.00 FL	*- FL
4	1		*PANEL, AIR GUIDE	Cracked	112.00 FL	*112.00 FL
5	1		*RADIATOR ASSY	Cracked	967.00 FL	*967.00 FL
6	1		*LLC 4L	Necessary	26.00 FL	*26.00 FL
7	1		*PANEL, AIR GUIDE, RH	Not Necessary	11.00 FL	*- FL
8	1		*PANEL, AIR GUIDE, LH	Not Necessary	11.00 FL	*- FL
9	1		*GRILLE, RADIATOR	Cracked	554.00 FL	*554.00 FL
10	1		*MARK, THREE - DIA	Not Necessary	69.00 FL	*69.00 FL
11	1		*BRACKET, FR BUMPER, LH	Not Necessary	13.00 FL	*- FL
12	1		*BRACKET, FR BUMPER, RH	Deformed	13.00 FL	*13.00 FL
13	1		*COVER, HEADLAMP SUPT PANEL	Not Necessary	62.00 FL	*- FL
14	1		*GRILLE, FR UNDER	Not Necessary	165.00 FL	*- FL
15	1		*GARNISH, FR BUMPER, LH	Not Necessary	127.00 FL	*- FL
16	1		*GARNISH, FR BUMPER, RH	Not Necessary	127.00 FL	*- FL
17	1		*FACE, FR BUMPER	Deformed	703.00 FL	*703.00 FL
18	1		*MARK, THREE - DIA	Necessary	69.00 FL	*- FL
19	1		*FENDER, FR RH	Bent	497.00 FL	*497.00 FL
20	1		*EMBLEM ECO	Necessary	17.00 FS	*17.00 FS
21	1		*HEADLAMP ASSY, LH	Not Necessary	660.00 FL	*- FL
22	1		*HEADLAMP ASSY, RH	Cracked	660.00 FL	*660.00 FL
23	1		*BODY KIT, ATTRAGE	Not Necessary	1,643.00 FN	*- FN
24	1		*FRONT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
25	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
26	1		*REINFORCEMENT, FR BUMPER	Bent	466.00 FL	*466.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	8,950.00	4,154.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,653.70	935.41
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	328.60	0.00
Total Parts (\$\$)	6,967.70	3,218.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BUMPER , FRONT BODY KITS RH FRONT FENDER, REPAIR RH FRONT DOOR, REPAIR LH FRONT FENDER.	New	2,250.00	900.00
2	TOP UP AIR CON GAS AND CHECK A/CON SYSTEM.	New	80.00	80.00
3	PAINT WORK SPRAY FRONT SUPPOR PANEL, FRONT BUMPER, FRONT BODY KITS, RH FRONT FENDER, RH FRONT DOOR, LH FRONT FENDER AND AFFECTED PORTION.	New	2,450.00	1,050.00
4	APPLY BODY SEALANT.	Repair	80.00	0.00
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.	New	30.00	30.00
6	PERFORM RUST PREVENTION.	New	80.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.	New	120.00	120.00
8	REPLACE FRONT REINFORCEMENT BEAM	New	450.00	450.00
9	SPRAY PAINT FRONT REINFORCEMENT BEAM	New	350.00	350.00
10	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER	New	100.00	100.00
Gross Labour Cost (S\$)			5,990.00	3,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >