



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



### ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11573/CHEE CHIN KHAM (XU JINQIAN) Reg No/Reg Date SMM3851T / 27/06/201 Date In/Mileage / 10311 Chassis No MMBSTA13AKH002145 Engine No 3A92UHT5876 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P01 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	13/10/2020/ 11:08	QUD	247 / DonBong	58430			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, 450 FRONT BUMPER, FRONT BODY KITS RH FRONT FENDER, REPAIR RH FRONT DOOR, REPAIR LH FRONT FENDER								900. 2250.00
E PNT88000 REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER								7 100.00
A 55900099 TOP UP AIR CON GAS AND CHECK A/CON SYSTEM								7 80.00
E PNT98000 PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BUMPER, FRONT BODY KITS, RH FRONT FENDER, RH FRONT DOOR, LH FRONT FENDER AND AFFECTED PORTION								1050 2450.00
M SUNDRY APPLY BODY SEALANT								x 80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								✓ 30.00
M SUNDRY PERFORM RUST PREVENTION								x 80.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								✓ 120.00
M SUNDRY SUPPLY FRONT NUMBER PLATE WITH FRAME								H / 50.00
M SUNDRY SUNDRIES								20 50.00
M	PANEL ASSY,FR END				1.00	1055.00	23.00	7 812.35
M	PANEL,HEADLAMP SUPPORT,UPR				1.00	65.00	23.00	7 50.05
M	CONDENSER ASSY,A/C REFRIGE				1.00	758.00	23.00	7 583.66
M	PANEL,AIR GUIDE				1.00	112.00	23.00	7 86.24
M	RADIATOR ASSY				1.00	967.00	23.00	7 744.59
M	LLC 4L				1.00	26.00	23.00	7 20.02
M	PANEL,AIR GUIDE,RH				1.00	11.00	23.00	7 8.47
M	PANEL,AIR GUIDE,LH				1.00	11.00	23.00	7 8.47

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



### ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11573/CHEE CHIN KHIAM (XU JINQIAN) Reg No/Reg Date SMM3851T / 27/06/201 Date In/Mileage / 10311 Chassis No MMBSTA13AKH002145 Engine No 3A92UHT5876 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim PO1 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	13/10/2020/ 11:08	QUD	247 / DonBong	58430
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M GRILLE, RADIATOR		1.00	554.00	23.00	426.58
M MARK, THREE-DIA		1.00	69.00	23.00	53.13
M BRACKET, FR BUMPER, LH		1.00	13.00	23.00	10.01
M BRACKET, FR BUMPER, RH		1.00	13.00	23.00	10.01
M COVER, HEADLAMP SUPT PANEL		1.00	62.00	23.00	47.74
M GRILLE, FR UNDER		1.00	165.00	23.00	127.05
M GARNISH, FR BUMPER, LH		1.00	127.00	23.00	97.79
M GARNISH, FR BUMPER, RH		1.00	127.00	23.00	97.79
M FACE, FR BUMPER		1.00	703.00	23.00	541.31
M MARK, THREE-DIA		1.00	69.00	23.00	53.13
M FENDER, FR RH		1.00	497.00	23.00	382.69
M EMBLEM ECO		1.00	17.00	00.00	17.00
M HEADLAMP ASSY, LH		1.00	660.00	23.00	508.20
M HEADLAMP ASSY, RH		1.00	660.00	23.00	508.20
M BODY KIT, ATTRAGE		1.00	1643.00	20.00	1314.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

SURVEYOR NAME: Taufik 97495749SURVEYOR SIGNATURE: [Signature]DATE: 13/10/20 R 430pmREMARKS: Ex: to be advise

Not Authorise, Renewal. Resurvey before paint.  
04 days  
taufik @ lkkauto.com.

Confirm &amp; accepted by

Nett	11,798.88
7% GST on	11798.88
Total Payable	12,624.80

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.