



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 5092B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	I40VC COVER ASSY - RR BUMPE	DENTED	1,106.00	1,106.00
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	I40VC LAMP ASSY - RR COMB O	CUT	697.80	697.80
	LESS 20% DISCOUNT		-365.16	-365.16
			1,460.64	1,460.64
<u>SPECIAL NETT ITEMS</u>				
1	I40VC PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
<u>LABOUR</u>				
	PANEL BEATING.		300.00	280.00
	SPRAY PAINTI CHARGE.		200.00	200.00
	CHECK ALL LIGHTING.		50.00	30.00
	LUBRICATE LOCK HINGES & HOOH LATCH.	NOT NECESSARY	80.00	-
			630.00	510.00
GRAND TOTAL			2,140.64	2,020.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,600.00

Report Ref No. NS/INC20011039/Eqd3s2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.