

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20011043/GTD3E2

Date: 11/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800130640
Claimant Vehicle No : SBS6670C	Insured Vehicle No : S1382R
Date of Loss: 28/09/2020	Nature of Claim: TP Claim No: 9579070965SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS6670C		
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 D (A)	Engine No:	HIDDEN
Reg. Date:	18/06/2013 (Man. Year: 2013)	Chassis No:	WEB62808323125100
Colour:	White	Odometer:	0 km
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70R22.5	Rear Tyre Size:	275/70R22.5(D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	890.00	890.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	890.00	890.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	62.30	62.30	0.00	0.00
Nett Amount (S\$)	952.30	952.30	0.00	0.00

INSPECTION

Date of Assignment:	12/10/2020	
Date Inspected:	12/10/2020	Inspected At: SBS Transit Ltd (AMK) 15 Ang Mo Kio Street 63 Singapore 569117
Estimated Period of Repair:	2.0 days	

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR COST	New	890.00	890.00
Gross Labour Cost (S\$)			890.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >