

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20011048/D3Q2

Date: 30/10/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713

Claimant
Vehicle No : SDU8722P

Insured Vehicle No : SLT4120M

Date of Loss: 06/10/2020

Nature of Claim: TP

Claim No: 629504

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDU8722P**

Make & Model: JAGUAR XJ, 3.0 Premium Luxury LWB (A)

Engine No: 0549046306DT

Reg. Date: 08/07/2011 (Man. Year: 2011)

Chassis No: SAJAC2253BNV21320

Colour: Metallic Gold

Odometer: 264677 km

Engine Capacity: 2993 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45Z R19

Rear Tyre Size:

275/40Z R19

Front Left Side: Pirelli 8 mm

Rear Left Side:

Pirelli 9 mm

Front Right Side: Pirelli 8 mm

Rear Right Side:

Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,324.00	5,535.00	12,789.00	69.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	680.00	1,250.00	64.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,254.00	6,215.00	14,039.00	69.31
Approved Total (Overridden) (S\$)		4,950.00		
(S\$)	20,254.00	4,950.00	15,304.00	75.56
+ GST 7.00/7.00% (S\$)	1,417.78	346.50	1,071.28	75.56
Nett Amount (S\$)	21,671.78	5,296.50	16,375.28	75.56

INSPECTION

Date of Assignment: 12/10/2020

Date Inspected: 14/10/2020 Inspected At:

MBM Wheelpower Pte Ltd (HQ)
160 Sin Ming Drive #06-02, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2020)
Parts:	143	JAGUAR XJ 3.0 Premium Luxury LWB (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDU8722P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	3,650.00 FL	*2,550.00 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	90.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	90.00 FL	*90.00 FL
4	1		*FRONT BUMPER FOG LAMP GARNISH RH	Serviceable	380.00 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP GARNISH CHROME TRIM RH	Serviceable	420.00 FL	*- FL
6	1		*FRONT BUMPER LOWER SPOILER RH	Serviceable	580.00 FL	*- FL
7	1		*FRONT BUMPER RADIATOR GRILLE	Serviceable	1,250.00 FL	*- FL
8	1		*FRONT BUMPER RADIATOR GRILLE LOGO	Serviceable	135.00 FL	*- FL
9	1		*FRONT FENDER RH	Repair	2,350.00 FL	*- FL
10	1		*FRONT FENDER INNER GARNISH RH	Serviceable	585.00 FL	*- FL
11	1		*HEADLAMP RH	Cracked	4,650.00 FL	*3,510.00 FL
12	1		*BONNET	Repair	5,850.00 FL	*- FL
13	1		*BONNET HINGE LH	Repair	165.00 FL	*- FL
14	1		*BONNET HINGE RH	Repair	165.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	20,360.00	6,150.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,036.00	615.00
Total Parts (\$\$)	18,324.00	5,535.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE ,REFIT & REPAIR REAR DAMAGED PORTIONS	New	800.00	300.00
2	CHECK & RECONNECT ALL NECESSARY WIRING	New	120.00	20.00
3	RESET ENGINE WARNING LIGHT (ABS,SRS,ECU MEMORY & ETC)	New	150.00	0.00
4	REMOVE & REPLACE BUMPER SENSORS	New	60.00	60.00
5	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	300.00
Gross Labour Cost (\$\$)			1,930.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >