

ASSIGNMENT

COE 2024 June

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____


Policy No. 1001338223Claims No. 248491

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 68 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHA 5006B Yr Regn: 2016 / June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685Colour Blue A/C: Insured / Std / NI / NASp. Reading 684918 T/Radio: Insured / Std / NI / NAEng/No: D4FDGU650722C/No: KMHLB41UMGU091397Gen. Cond: Good Fair / Poor / BurntSteering: In order Jammed / Leaked / Burnt orBrake: In order Jammed / Leaked / Burnt orModi: Nil S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 10/10/2020 D.O.A. 14/10/2020Survey held at Bigrost sin King

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MSIG SLA1683A

09/11/20 @ 4.21pm revised to Chhia Nyak Pui via Mentri.

20/04/2021 Jpax 1/S 9300 - with 6 days 7 in (Red \$960748,512)

Date/Time, File Pass to?

☐ : Prel. Report

12/04/2021

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RG, SI

Photos

Others

TOTAL

Report Format: UBR-TPLump Sum / I.B.L. (\$) 9300Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 12-Oct-20

INSURANCE: MSIG

MODEL: HYUNDAI I40

VEHICLE NO.: SHA 5006 B

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BONNET <i>Dented</i>	1	\$2,265.90	\$2,265.90
BONNET RUBBER (LH) <i>HH</i>	1	\$35.70	\$35.70
BONNET RUBBER (RH) <i>HH</i>	1	\$35.70	\$35.70
BONNET HINGE (LH/RH) <i>HH</i>	2	\$126.70	\$253.40
BONNET LOCK <i>HH</i>	1	\$142.40	\$142.40
BONNET INSULATOR <i>HH</i>	1	\$202.50	\$202.50
BONNET INSULATOR CLIP 10 PCS <i>HH</i>	1	\$36.80	\$36.80
BONNET SEAL <i>HH</i>	1	\$31.90	\$31.90
BONNET INSULATOR CLIPS <i>HH</i>	1	\$15.00	\$15.00
RADIATOR GRILLE H EMBLEM <i>HH</i>	1	\$129.50	\$129.50
RADIATOR GRILLE <i>broken</i> 1110.50	1	\$1,480.00	\$1,480.00
FRONT BUMPER COVER <i>Punctured</i>	1	\$1,052.20	\$1,052.20
FRONT BUMPER SPONGE <i>HH</i>	1	\$379.20	\$379.20
FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	\$588.40	\$588.40
FRONT BUMPER GRILLE (LH/RH) <i>HH</i>	2	\$149.20	\$298.40
FRONT BUMPER LIP <i>HH</i>	1	\$152.00	\$152.00
FRONT BUMPER BRACKET TOP (LH/RH) <i>HH</i>	2	\$44.80	\$89.60
FRONT BUMPER BRACKET (LH/RH) <i>HH</i>	2	\$49.20	\$98.40
FRONT BUMPER RETAINER MOUNTING <i>HH</i>	1	\$76.20	\$76.20
FRONT BUMPER GRILLE AIR DUCT (RH) <i>HH</i>	1	\$126.20	\$126.20
HEADLAMP SUPPORT PANEL ASSY <i>broken</i> <i>Dented</i>	1	\$907.40	\$907.40
HEADLAMP (RH) <i>mainly crack</i> 1388.00	1	\$2,776.00	\$2,776.00
HEADLAMP SUPPORT TOP COVER <i>HH</i>	1	\$222.60	\$222.60
RADIATOR <i>2 1st</i> 708.50	1	\$1,637.20	\$1,637.20
RADIATOR GUARD (LH/RH) <i>HH</i>	2	\$76.50	\$153.00
COOLANT <i>HH</i>	1	\$ 45.00	\$ 45.00
FRONT FENDER (RH) <i>Dented</i>	1	\$566.30	\$566.30
FRONT FENDER SHIELD (RH) <i>HH</i>	1	\$174.90	\$174.90
AIRCON CONDENSER <i>2 1st</i>	1	\$947.80	\$947.80
INTER COOLER <i>HH crack</i>	1	\$1,032.50	\$1,032.50
SUB TOTAL 1121.86			\$15,952.10
LESS 20%			\$3,190.42
DISCOUNTED TOTAL 8974.88			\$12,761.68
FRONT NUMBER PLATE <i>broken</i> SN	1	\$25.00	\$25.00
FRONT NO. PLATE TRIM COVER <i>broken</i> SN	1	\$30.00	\$30.00
FRONT FENDER ADVERTISEMENT LOGO <i>HH</i> SN	1	\$100.00	\$100.00
SUB TOTAL 145.00			\$155.00
Labour Charge			

Panel Beating	1	\$1,400.00	\$1,400.00	700/-
Spray Painting Charge	1	\$1,200.00	\$1,200.00	600/-
Wiring Charge	1	\$160.00	\$160.00	30/-
Tuff Kote	1	\$160.00	\$160.00	40/-
Towing Charge	1	\$80.00	\$80.00	40/-
Remove/Refix Radiator	1	\$90.00	\$90.00	50/-
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00	80/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	44
TOTAL LABOUR			\$3,770.00	
ESTIMATE TOTAL			\$ 16,686.68	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

14/10/2020 @ 0900hrs

1/14 Autocash

1/14

6

8 dgs.

2/14

2/14 Auto

8

Provide book value

10619.88

Supp 1110.40

11730.28

L/S 9300/-

18907-48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR SUPPLEMENTARY

DATE: 14-Oct-20

INSURANCE: MSIG

MODEL: HYUNDAI I40

VEHICLE NO.: SHA 5006 B (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
HEADLAMP (LH) <i>monday crack</i> 1388.00	1	\$2,776.00	\$2,776.00
SUB TOTAL			\$2,776.00
LESS 20%			\$555.20
DISCOUNTED TOTAL			\$2,220.80

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

[Signature]
Nga
2KK Auto

1388.00
20%, 1110.40

[Signature]