

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20011052/EBS3Q2  
**Date:** 16/03/2021

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800117459
<b>Claimant</b>		
<b>Vehicle No :</b> SHB4387C	<b>Insured Vehicle No :</b>	SME6474X
Date of Loss: 12/10/2020	Nature of Claim: TP	Claim No: 2539134668SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB4387C</b>		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR2B82933
Reg. Date:	06/12/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU403077631
Colour:	Blue	Odometer:	144670 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,211.72	1,211.72	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	720.00	550.00	170.00	23.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,931.72</b>	<b>1,761.72</b>	<b>170.00</b>	<b>8.80</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>135.22</b>	<b>123.32</b>	<b>11.90</b>	<b>8.80</b>
<b>Nett Amount (S\$)</b>	<b>2,066.94</b>	<b>1,885.04</b>	<b>181.90</b>	<b>8.80</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$126.47/day) (S\$)</b>		252.94		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,239.98</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,230.00</b>		

#### INSPECTION

Date of Assignment:	13/10/2020	
Date Inspected:	13/10/2020 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969

Estimated Period of Repair: 2.0 days

---

**Adjuster:** CHEN TSUE YEE**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	458.60 FL	*458.60 FL
2	1		*REAR BUMPER CENTER -BLACK	Cut	552.60 FL	*552.60 FL
3	1		*REAR BUMPER TOW COVER	Cut	82.70 FL	*82.70 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	318.80 FL	*318.80 FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>1,570.40</b>	<b>1,570.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	358.68	358.68
<b>Total Parts (\$)</b>	<b>1,211.72</b>	<b>1,211.72</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	320.00
2	SPRAYPAINT CHARGE	New	250.00	200.00
3	R/I REVERSE SENSOR	New	120.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>720.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >