

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20011060/UQD3Q2

**Date:** 02/11/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713MKF

**Claimant**  
**Vehicle No :** SLM4832D

**Insured Vehicle No :** SLG6463D

Date of Loss: 10/10/2020

Nature of Claim: TP

Claim No: 629737

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM4832D**

Make & Model: MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A)

Engine No: 4A92CN2338

Reg. Date: 31/03/2017 (Man. Year: 2016)

Chassis No: JMYSRCY1AGU006402

Colour: Black

Odometer: 57440 km

Engine Capacity: 1590 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/40 ZR18

Rear Tyre Size: 225/40 ZR18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,565.15	3,586.50	5,978.65	62.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	1,460.00	1,050.00	41.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,075.15</b>	<b>5,046.50</b>	<b>7,028.65</b>	<b>58.21</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,075.15</b>	<b>4,000.00</b>	<b>8,075.15</b>	<b>66.87</b>

### INSPECTION

Date of Assignment: 13/10/2020

Date Inspected: 13/10/2020 Inspected At:

Ping Motor Pte Ltd (HQ)  
1 Kaki Bukit Avenue 6, #01-25  
Autobay @ Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2020)
<b>Parts:</b>	143	MITSUBISHI LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLM4832D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER CENTRE BEAM	Bent	138.00 FL	*138.00 FL
2	1		*REAR BUMPER REINFORCEMENT BEAM	Bent	254.00 FL	*254.00 FL
3	1		*REAR BUMPER SIDE RETAINER L/R	N/s Bent	64.00 FL	*32.00 FL
4	2		*REAR NO PLATE LAMP L/R	Not Necessary	90.00 FL	*- FL
5	2		*REAR NO PLATE LAMP BRACKET L/R	Not Necessary	80.00 FL	*- FL
6	1		*REAR BOOT LID KEYLESS SMART	Cracked	158.00 FL	*158.00 FL
7	1		*REAR BOOT LID WEATHER STRIP	Twisted	186.00 FL	*186.00 FL
8	1		*REAR END PANEL	Repair	689.00 FL	*- FL
9	1		*REAR END PANEL INNER GARNISH	Twisted	241.00 FL	*241.00 FL
10	4		*REAR END PANEL INNER GARNISH CLIP	Not Necessary	22.00 FL	*- FL
11	1		*REAR FENDER INNER TRIM LH	Not Necessary	508.00 FL	*- FL
12	5		*REAR FENDER INNER TRIM CLIP LH	Not Necessary	27.50 FL	*- FL
13	1		*REAR FENDER INNER SHIELD LH	Torn	83.00 FL	*83.00 FL
14	4		*REAR FENDER INNER SHIELD CLIP LH	Not Necessary	22.00 FL	*- FL
15	1		*REAR TAILLAMP LH	Cracked	897.00 FL	*548.00 FL
16	1		*REAR TAILLAMP PANEL LH	Repair	179.00 FL	*- FL
17	1		*REAR SPARE TYRE TOP BOARD	Torn	245.00 FL	*245.00 FL
18	1		*REAR CUSTOMISED BUMPER	Torn	2,300.00 FS	*1,500.00 FS
19	1		*REAR CARBON FIBRE BOOT LID	Serviceable	2,800.00 FS	*- FS
20	1		*REAR NO PLATE (CHROME) }	Cracked	120.00 FS	*40.00 FS
21	1		*REAR CARBON FIBRE FRAME }		50.00 FS	*- FS
22	1		*REAR BUMPER LED LIGHT	Cracked	150.00 FS	*100.00 FS
23	1		*REAR BUMPER SIDE REFLECTOR LAMP ASSY	Repeated	250.00 FS	*- FS
24	1		*REAR BUMPER REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
25	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,953.50</b>	<b>3,775.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	388.35	188.50
<b>Total Parts (\$\$)</b>	<b>9,565.15</b>	<b>3,586.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRINGS	New	80.00	30.00
2	TO REMOVE AND REPLACE AND REINSTALL REAR REVERSE SENSOR	New	120.00	50.00
3	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS,GARNISHES,SEATS,ETC FOR NECESSARY REPAIRS	New	160.00	80.00
4	TO DISMANTLE,REPLACE FOR REAR BUMPER BODYKIT	New	150.00	0.00
5	TO STRAIGHTEN,REPAIR,REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	600.00
6	TO SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	700.00
<b>Gross Labour Cost (\$)</b>			<b>2,510.00</b>	<b>1,460.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**