

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 30 Oct 2020

Preliminary Advice

Insured Vehicle No	: SLG6463D	Accident Date	: 10/10/2020
TP Vehicle No	: SLM4832D	Assignment Date	: 13/10/2020
Make	: MITSUBISHI LANCER	Est. Duration of Repair	: 4
Date of Inspection	: 13/10/2020		
Inspection At	: PING MOTOR PTE LTD (HQ) 1 KAKI BUKIT AVENUE 6, #01-25 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,825.15
Revised Amount	:S\$	5,046.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,046.50
 Lump Sum Repair	 :S\$	 4,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.