

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20011061/AGS3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMC1320A	Insured Vehicle No :	SHD4864G
Date of Loss: 09/10/2020	Nature of Claim: TP	Claim No: MCT20100142

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC1320A		
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Engine No:	FB20YD98172
Reg. Date:	28/06/2018 (Man. Year: 2018)	Chassis No:	JF1SJ5KC5JG110463
Colour:	Blue	Odometer:	49891 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,207.70	4,930.00	5,277.70	51.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	2,050.00	620.00	23.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,877.70	6,980.00	5,897.70	45.80
Approved Total (Overridden) (\$\$)		5,500.00		
(\$\$)	12,877.70	5,500.00	7,377.70	57.29
+ GST 7.00/7.00% (\$\$)	901.44	385.00	516.44	57.29
Nett Amount (\$\$)	13,779.14	5,885.00	7,894.14	57.29
+ Loss of Use (8.0 x S\$80.00/day) (\$\$)		640.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		6,532.45		
Global Sum Settlement (\$\$)		6,500.00		

INSPECTION

Date of Assignment:	12/10/2020	
Date Inspected:	12/10/2020 Inspected At:	Green Forest Automobile Pte Ltd (Kaki Bukit)
		8 Kaki Bukit Avenue 4, #05-25,,
		Premier@Kaki Bukit
		Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Dec 2020)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC1320A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,252.20 F	*1,252.20 FL
2	1		*REAR BOOT LID INNER LOCK	Not Necessary	285.20 F	*- FL
3	1		*REAR BOOT LID WINDSCREEN MOULDING	Necessary	122.20 F	*122.20 FL
4	1		*REAR BOOT LID EMBLE LOGO	Necessary	83.60 F	*83.60 FL
5	1		*REAR BOOT LID SUBARU LOGO	Necessary	60.00 F	*60.00 FL
6	1		*REAR BOOT LID FORESTER LOGO	Necessary	49.50 F	*49.50 FL
7	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	425.10 F	*425.10 FL
8	1		*REAR TAIL LAMP	O/S Cracked	1,132.40 F	*437.00 FL
9	1		*REAR FENDER INNER TRIM BOARD -RH	Not Necessary	544.00 F	*- FL
10	8		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	44.80 F	*- FL
11	1		*REAR BUMPER	Distorted	950.00 F	*710.00 FL
12	1		*REAR BUMPER REFLECTOR	O/S Cracked	110.40 F	*55.20 FL
13	1		*REAR BUMPER SIDE BRACKET	O/S Damaged	176.40 F	*35.00 FL
14	1		*REAR BUMPER INNER SPONGE	Not Necessary	155.20 F	*- FL
15	8		*REAR BUMPER CLIPS	Necessary	44.80 F	*44.80 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	425.00 F	*425.00 FL
17	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
18	1		*REAR BUMPER TOWING COVER	Not Necessary	65.00 F	*- FL
19	1		*REAR BUMPER TOP CHROME PANEL	Distorted	422.60 F	*422.60 FL
20	1		*REAR BUMPER LOWER GARNISH	Distorted	288.00 F	*288.00 FL
21	1		*REAR BUMPER LOWER COVER	Not Necessary	325.00 F	*- FL
22	1		*REAR END PANEL	Distorted	462.30 F	*462.30 FL
23	1		*END PANEL TOP GARNISH	Not Necessary	285.00 F	*- FL
24	1		*REAR EXHAUST SILENCER	Dented	855.00 F	*855.00 FL
25	1		*REAR EXHAUST CENTRE PIPE	Not Necessary	974.00 F	*- FL
26	1		*REAR EXHAUST CHROME PIPE	Bent	185.00 F	*185.00 FL
27	3		*REAR EXHAUST MOUNTING	Not Necessary	135.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,207.70	6,112.50
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,182.50
Total Parts (\$\$)	10,207.70	4,930.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
2	GUM	New	50.00	50.00
3	REMOVE & REFIX REAR CUSHION	New	120.00	60.00
4	REMOVE & REFIX REAR REVERSE SENSOR	New	120.00	50.00
5	TUFF KOTE	New	120.00	60.00
6	TO CHECK WIRING SYSTEM	New	60.00	30.00
7	TO REMOVE & REFIX REAR EXHAUST	New	280.00	80.00
8	PANEL BEATING	New	900.00	800.00
9	SPRAY PAINTING	New	900.00	800.00
Gross Labour Cost (\$)			2,670.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >