

Speed Auto Work
(Co Reg. No. 5321801E)
Blk 90 Bedok North Street 4
#13-1537 Singapore 460090
Tel : 6789 5155 Fax : 6783 5155

TO : CHINA TAIPING ATTENTION : MOTOR CLAIMS DEPARTMENT ESTIMATE REPORT : <u>OWNER PARTICULAR</u> NAME : Denise ADDRESS : TEL. NO. : OWNER INSUANCE : CHINA TAIPING POLICY NO. : DMCVSNW00019152000 PERSON INCHARGE :	DATE : 8-Oct-20 JOB TYPE : T/P CLAIMS <u>VEHICLE DETAILS</u> VEHICLE NO. : GBC8630P MODEL / MAKE : TOYOTA DYNA CHASSIS NO. : JTFAT35Y00K201548 <u>ACCIDENT DETAIL</u> DATE : 8-Oct-20 TIME : 08:40hrs
--	--

QUOTATION SUMMARY **PAGE 01**

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR RH <i>Dented</i>	1	\$ 1,218.90	\$ 1,218.90 ✓
2	FRONT DOOR GLASS OUTER MOULDING RH <i>Not m</i>	1	\$ 168.60	\$ 168.60 +
3	FRONT DOOR HINGES LOWER RH <i>Not m</i>	1	\$ 78.90	\$ 78.90 +
4	FRONT DOOR INNER TRIM BOARD RH <i>Not m</i>	1	\$ 942.60	\$ 942.60 +
5	FRONT DOOR SPEAKER RH <i>Not m</i>	1	\$ 454.10	\$ 454.10 +
6	FRONT DOOR LOWER RUBBER SEAL RH <i>Not m</i>	1	\$ 164.40	\$ 164.40 +
7	FRONT DOOR WEATHERSTRIP RH <i>Not m</i>	1	\$ 278.40	\$ 278.40 +
8	FRONT DOOR MECHANISM LOCK RH <i>Not m</i>	1	\$ 399.50	\$ 399.50 +
9	FRONT DOOR PILLAR PANEL 'OUTER' RH <i>Repair</i>	1	\$ 1,944.30	\$ 1,944.30 +
10	FRONT DOOR PILLAR WATER STRIP RH <i>Not m</i>	1	\$ 227.20	\$ 227.20 +
11	FRONT DOOR STEP PANEL RH <i>Not m</i>	1	\$ 148.20	\$ 148.20 +
12	FRONT DOOR STEP PANEL GARNISH RH <i>Not m</i>	1	\$ 291.80	\$ 291.80 +
13	FRONT WINDSCREEN GLASS RUBBER MOULDING <i>Not m</i>	1	\$ 276.30	\$ 276.30 +
14	FRONT CORNER SIDE PANEL RH <i>Repair</i>	1	\$ 233.90	\$ 233.90 +
15	FRONT GRILLE <i>Not m</i>	1	\$ 429.80	\$ 429.80 +
16	FRONT GRILLE EMBLEM <i>Not m</i>	1	\$ 54.70	\$ 54.70 +
17	FRONT HEADLAMP RH <i>Not m</i>	1	\$ 328.95	\$ 328.95 ✓
18	FRONT HEADLAMP LOWER RUBBER SEAL RH <i>Not m</i>	1	\$ 47.20	\$ 47.20 +
19	FRONT HEADLAMP HOLDER RH <i>Not m</i>	1	\$ 9.80	\$ 9.80 +
20	FRONT HEADLAMP INNER PANEL RH <i>Repair</i>	1	\$ 261.70	\$ 261.70 +
21	FRONT BUMPER <i>Distorted</i>	1	\$ 356.90	\$ 356.90 ✓
22	FRONT BUMPER BRACKET LH/RH <i>RH Bent</i>	2	\$ 193.20	\$ 386.40 <i>193.20</i>

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
23	FRONT CABIN WHEEL ARCH PANEL RH <i>new</i>	1	\$ 538.90	\$ 538.90 <i>+</i>
24	FRONT CABIN WHEEL ARCH PANEL TOP GARNISH RH <i>new</i>	1	\$ 356.50	\$ 356.50 <i>+</i>
25	FRONT CABIN WHEEL ARCH PANEL RUBBER SEAL RH <i>new</i>	1	\$ 21.30	\$ 21.30 <i>+</i>
26	FRONT DIESEL VACUUM TANK <i>new</i>	1	\$ 200.90	\$ 200.90 <i>+</i>
TOTAL PRICE				\$ 9,820.15
LESS -25%				\$ (2,455.04)
SUB TOTAL PRICE				<u>\$ 7,365.11</u>

2389.75
1792.31

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR COMPANY DETAIL STICKER RH <i>new</i>	1	\$ 180.00	\$ 180.00 <i>30</i>
2	FRONT DOOR STEP PANEL GARNISH CLIPS SET RH <i>new</i>	1	\$ 40.00	\$ 40.00 <i>10</i>
3	FRONT GRILLE CLIPS SET <i>new</i>	1	\$ 60.00	\$ 60.00 <i>+</i>
4	FRONT BUMPER NUMBER PLATE <i>new</i>	1	\$ 45.00	\$ 45.00 <i>+</i>
5	FRONT CABIN WHEEL ARCH PANEL TOP GARNISH CLIPS SET RH <i>new</i>	1	\$ 60.00	\$ 60.00 <i>+</i>
6	FRONT CABIN WHEEL ARCH PANEL SEALANT RH <i>new</i>	1	\$ 100.00	\$ 100.00 <i>+</i>
7	FRONT CABIN FLOOR PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
TOTAL				<u>\$ 635.00</u>

60

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,000.00	<i>600.</i>	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 800.00	<i>600</i>	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 105.00	<i>50</i>	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	<i>30</i>	
TO DISMANTLE & REINSTALL FRONT DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING	\$ 250.00	<i>80</i>	
TO DISMANTLE & REINSTALL FRONT WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00	<i>x.</i>	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	<i>50</i>	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	<i>x.</i>	

TOTAL

\$ 2,745.00

1410

QUOTATION SUMMARY

PAGE 03

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	8,000.11
TOTAL LABOUR COST	:	\$	2,745.00
TOTAL REPAIR COST	:	\$	10,745.11

APPROVED DETAILS

NO. OF REPAIR DAYS : DAYS

REPAIR UNDER : PART BY PART OR LUMPSUM

DATE / TIME OF SURVEY :

SURVEYED BY / FROM : Adrian G

CONTACT NUMBER : 2/s 13/10/20

FAX NUMBER : 05 Days.

EMAIL ADDRESS :

DATE / TIME OF RE-SURVEY : total 3262.31

EXCESS : c/s: 2.6K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: