

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011064/ATD3Q2

Date: 04/11/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00048902000

Claimant Vehicle No : GBC8630P **Insured Vehicle No :** SMT2817M

Date of Loss: 08/10/2020 Nature of Claim: TP Claim No: SNM20D203793/C02/CHUAKK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC8630P**

Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2352484

Reg. Date: 30/12/2013 (Man. Year: 2013) Chassis No: JTFAT35Y60K202705

Colour: Silver Odometer: 208942 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15C Rear Tyre Size: 155R12C

Front Left Side: Michelin 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,000.11	1,852.31	6,147.80	76.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,745.00	1,410.00	1,335.00	48.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,745.11	3,262.31	7,482.80	69.64
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	10,745.11	2,600.00	8,145.11	75.80
+ GST 7.00/7.00% (S\$)	752.16	182.00	570.16	75.80
Nett Amount (S\$)	11,497.27	2,782.00	8,715.27	75.80

INSPECTION

Date of Assignment: 02/11/2020

Date Inspected: 13/10/2020 Inspected At:

Speed Auto Works - Kaki Bukit (HQ)
8 Kaki Bukit Ave 4 #08-46 Premier @
Kaki Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Nov 2020)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC8630P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	1,218.90 FL	*1,218.90 FL
2	1		*FRONT DOOR GLASS OUTER MOULDING RH	Not Necessary	168.60 FL	*- FL
3	1		*FRONT DOOR HINGES LOWER RH	Not Necessary	78.90 FL	*- FL
4	1		*FRONT DOOR INNER TRIM BOARD RH	Not Necessary	942.60 FL	*- FL
5	1		*FRONT DOOR SPEAKER RH	Not Necessary	454.10 FL	*- FL
6	1		*FRONT DOOR LOWER RUBBER SEAL RH	Not Necessary	164.40 FL	*- FL
7	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	278.40 FL	*- FL
8	1		*FRONT DOOR MECHANISM LOCK RH	Not Necessary	399.50 FL	*- FL
9	1		*FRONT DOOR PILLAR PANEL OUTER RH	Repair	1,944.30 FL	*- FL
10	1		*FRONT DOOR PILLAR WATER STRIP RH	Not Necessary	227.20 FL	*- FL
11	1		*FRONT DOOR STEP PANEL RH	Not Necessary	148.20 FL	*- FL
12	1		*FRONT DOOR STEP PANEL GARNISH RH	Cut	291.80 FL	*291.80 FL
13	1		*FRONT WINDSCREEN GLASS RUBBER MOULDING	Not Necessary	276.30 FL	*- FL
14	1		*FRONT CORNER SIDE PANEL RH	Repair	233.90 FL	*- FL
15	1		*FRONT GRILLE	Not Necessary	429.80 FL	*- FL
16	1		*FRONT GRILLE EMBLEM	Not Necessary	54.70 FL	*- FL
17	1		*FRONT HEADLAMP RH	Cut	328.95 FL	*328.95 FL
18	1		*FRONT HEADLAMP LOWER RUBBER SEAL RH	Not Necessary	47.20 FL	*- FL
19	1		*FRONT HEADLAMP HOLDER RH	Not Necessary	9.80 FL	*- FL
20	1		*FRONT HEADLAMP INNER PANEL RH	Repair	261.70 FL	*- FL
21	1		*FRONT BUMPER	Distorted	356.90 FL	*356.90 FL
22	1		*FRONT BUMPER BRACKET LH/RH	O/s Bent	386.40 FL	*193.20 FL
23	1		*FRONT CABIN WHEEL ARCH PANEL RH	Not Necessary	538.90 FL	*- FL
24	1		*FRONT CABIN WHEEL ARCH PANEL TOP GARNISH RH	Not Necessary	356.50 FL	*- FL
25	1		*FRONT CABIN WHEEL ARCH PANEL RUBBER SEAL RH	Not Necessary	21.30 FL	*- FL
26	1		*FRONT DIESEL VACUUM TANK	Not Necessary	200.90 FL	*- FL
27	1		*FRONT DOOR COMPANY DETAIL STICKER RH	Necessary	180.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT DOOR STEP PANEL GARNISH CLIPS SET RH	Necessary	40.00 FS	*10.00 FS
29	1		*SET FRONT GRILLE CLIPS	Not Necessary	60.00 FS	*- FS
30	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	45.00 FS	*- FS
31	1		*FRONT CABIN WHEEL ARCH PANEL TOP GARNISH CLIPS SET RH	Not Necessary	60.00 FS	*- FS
32	1		*FRONT CABIN WHEEL ARCH PANEL SEALANR RH	Not Necessary	100.00 FS	*- FS
33	1		*FRONT CABIN FLOOR PANEL SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,455.15	2,449.75
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,455.04	597.44
Total Parts (\$\$)	8,000.11	1,852.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,000.00	600.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	800.00	600.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	105.00	50.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO DISMANTLE & REINSTALL FRONT DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING	New	250.00	80.00
6	TO DISMANTLE & REINSTALL FRONT WINDSCREEN PERFORM WITH WATER LEAK TEST	New	150.00	0.00
7	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	280.00	50.00
8	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
Gross Labour Cost (\$\$)			2,745.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >