

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20011065/Evd3s2

189556			Date: 30-10-2020		
			Code: INC4		
1.					
	Insured Veh.	SMQ 4834R	Veh. Inspected	SH 6339S	
	Policy No.	5114245836	Coverage (\$)	0.00	
	Claim No.	MT/1106530-002	Excess (\$)	0.00	
	Assign From		Assign Date	13/10/2020	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI 140	c.c	1685	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	KMHLB41UMHU096475	Colour	BLUE	
	Odometer	222605	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	GOODYEAR	5 mm	
	L/H Front Tyre	205/60 R16	GOODYEAR	5 mm	
	R/H Rear Tyre	205/60 R16	GOODYEAR	5 mm	
	L/H Rear Tyre	205/60 R16	GOODYEAR	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	08/10/2020	Inspection Date	13/10/2020	
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD		
		59 LOYANG DRIVE SINGAPORE 508969			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				