

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011066/ATD3Q2

Date: 30/11/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNA00096122000	
Claimant Vehicle No : SLG6607G	Insured Vehicle No : GU5305U	
Date of Loss: 08/10/2020	Nature of Claim: TP	Claim No: SNM20D203815/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG6607G		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	1ZRY334598
Reg. Date:	10/10/2016 (Man. Year: 2016)	Chassis No:	MR053REH104558688
Colour:	Silver	Odometer:	223615 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,234.25	898.50	335.75	27.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	780.00	570.00	42.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,584.25	1,678.50	905.75	35.05
Approved Total (Overridden) (\$\$)		1,300.00		
(\$\$)	2,584.25	1,300.00	1,284.25	49.70
+ GST 7.00/7.00% (\$\$)	180.90	91.00	89.90	49.70
Nett Amount (\$\$)	2,765.15	1,391.00	1,374.15	49.70

INSPECTION

Date of Assignment:	23/10/2020	
Date Inspected:	13/10/2020 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG6607G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT LH DOOR	Dented	1,135.00 FL	*1,135.00 FL
2	1	*FRONT LH DOOR BLACK TAPE	Necessary	63.00 FL	*63.00 FL
3	1	*FRONT LH DOOR OUTER CHROME MOULDING	Not Necessary	93.00 FL	*- FL
4	1	*FRONT LH DOOR VERTICAL PROTECTOR GARNISH	Not Necessary	93.00 FL	*- FL
5	1	*FRONT LH DOOR WEATHER STRIP SEAL	Not Necessary	195.00 FL	*- FL
6	1	*SET FRONT LH DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,629.00	1,198.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	394.75	299.50
Total Parts (\$\$)	1,234.25	898.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TRANSFER DOOR GLASS,REGULATOR GEAR,MOTOR,RAILING,CHANNEL,TRIM BOARD,MECHANISM LOCK AND HANDLE	New	100.00	80.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	700.00	400.00
3	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	500.00	300.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	50.00	0.00
Gross Labour Cost (\$\$)			1,350.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >