

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20011072/ERA3Q2
Date: 19/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070006400
Claimant Vehicle No :	SH9589S	Insured Vehicle No :	SMH3043K
Date of Loss:	13/10/2020	Nature of Claim:	TP
		Claim No:	2225841696SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH9589S	Engine No:	D4FDGU700052
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU089924
Reg. Date:	26/05/2016 (Man. Year: 2016)	Odometer:	537570 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,134.80	952.40	182.40	16.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	930.00	730.00	200.00	21.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,064.80	1,682.40	382.40	18.52
Approved Total (Overridden) (S\$)		1,350.00		

(S\$)	2,064.80	1,350.00	714.80	34.62
+ GST 7.00/7.00% (S\$)	144.54	94.50	50.04	34.62
Nett Amount (S\$)	2,209.34	1,444.50	764.84	34.62
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 13/10/2020

Date Inspected: 14/10/2020

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ASSY -RR BUMPE	Dented	1,106.00 FL	*1,106.00 FL
2	1		*COVER -RR BUMPER LWR	Not Necessary	228.00 FL	*- FL
3	10		*HYUNDAI BUMPER COVER CLIP	Necessary	22.00 FL	*22.00 FL
4	1		*PROTECTOR MAT	Necessary	50.00 FS	*50.00 FS
					Sub Total (\$\$)	1,406.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	271.20
					Total Parts (\$\$)	1,134.80

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	300.00	280.00
2	SPRAYPAINT CHARGE	New	300.00	200.00
3	RENEW ADVERTISEMENT STICKER -BUMPER	New	50.00	50.00
4	RENEW ADVERTISEMENT STICKER -FENDER	New	200.00	200.00
5	REMOVE/REFIX REVERSE SENSOR ASSY	New	80.00	0.00
Gross Labour Cost (S\$)			930.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >