

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20011074/T1VD3Q2

Date: 30/10/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SMT419S

Insured Vehicle No :

XE568T

Date of Loss: 22/09/2020

Nature of Claim:

TP

Claim No:

N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMT419S

Make & Model: MITSUBISHI ECLIPSE CROSS, 1.5 (A)

Engine No: 4B40HR2506

Reg. Date: 25/03/2020 (Man. Year: 2019)

Chassis No: JMAXTGK1WLZ001769

Colour: Bronze

Odometer: 5813 km

Engine Capacity: 1499 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18

Rear Tyre Size:

225/50 R18

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,387.00	3,048.30	338.70	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	850.00	650.00	43.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,887.00	3,898.30	988.70	20.23
Approved Total (Overridden) (\$\$)		3,100.00		
(\$\$)	4,887.00	3,100.00	1,787.00	36.57
+ GST 7.00/7.00% (\$\$)	342.09	217.00	125.09	36.57
Nett Amount (\$\$)	5,229.09	3,317.00	1,912.09	36.57

INSPECTION

Date of Assignment: 12/10/2020

Date Inspected: 14/10/2020 Inspected At:

Ban Choon Motor Works (HQ)

Blk 3 Pioneer Road North #01-15

Singapore 628457

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2020)
Parts:	143	mitsubishi eclipse cross 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT419S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Cut	603.00 F	*603.00 FN
2	1		*LH HEADLAMP	Cut	2,095.00 F	*2,095.00 FN
3	1		*FRONT BUMPER CENTRE GARNISH	Cut	355.00 F	*355.00 FN
4	1		*FRONT BUMPER LOWER GARNISH	Cut	334.00 F	*334.00 FN

F=Franchise part. N=NettItemDisc.

Sub Total (S\$)	3,387.00	3,387.00
- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00	338.70
Total Parts (S\$)	3,387.00	3,048.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING AND STRAIGHTENING OF ALL NECESSARY DAMAGED PARTS .TO CHANGING OF THE ABOVE PARTS	New	600.00	400.00
2	TO PUTTY AND SPRAY PAINTING ON ACCIDENT DAMAGED PARTS	New	900.00	450.00
Gross Labour Cost (\$)			1,500.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >