

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20011076/T1QD3E2

Date: 22/03/2021

REFERENCE

Insured/Claimant:	AHMED ZAKARIA FIRFIRE	Policy No:	1900163755	
Date of Loss:	11/10/2020	Nature of Claim:	OD	Claim No: 8677603883SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML3246X	Engine No:	3A92UHS0991
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH001511
Reg. Date:	15/05/2019 (Man. Year: 2018)	Odometer:	33340 km
Colour:	Maroon		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$54,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,247.91	8,145.62	2,102.29	20.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,180.00	8,280.00	3,900.00	32.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,427.91	16,425.62	6,002.29	26.76
- Excess (\$\$)	1,800.00	1,800.00	0.00	0.00
(\$\$)	20,627.91	14,625.62	6,002.29	29.10
+ GST 7.00/7.00% (\$\$)	1,443.95	1,023.79	420.16	29.10
Nett Amount (\$\$)	22,071.86	15,649.41	6,422.45	29.10

INSPECTION

Date of Assignment:	13/10/2020	
Date Inspected:	13/10/2020 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BODY PNL SEALANT	Necessary	80.00 FS	*80.00 FS
2	1		*FRT NUMBER PLATE WITH CASING	Missing	50.00 FS	*50.00 FS
3	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
4	1		*FACE, FR BUMPER	Deformed	703.00 FL	*703.00 FL
5	5		*CLIP, FR BUMPER	Necessary	20.00 FL	*20.00 FL
6	1		*COVER, HEADLAMP SUPT PANEL	Bent	62.00 FL	*62.00 FL
7	1		*GRILLE, FR UNDER	Deformed	165.00 FL	*165.00 FL
8	1		*BRACKET, FR BUMPER, LH	Deformed	13.00 FL	*13.00 FL
9	1		*BRACKET, FR BUMPER, RH	Deformed	13.00 FL	*13.00 FL
10	1		*GARNISH, FR BUMPER, LH	Not Necessary	127.00 FL	*- FL
11	1		*GARNISH, FR BUMPER, RH	Not Necessary	127.00 FL	*- FL
12	1		*MARK, THREE-DIA	Necessary	69.00 FL	*69.00 FL
13	1		*GRILLE, RADIATOR	Cracked	554.00 FL	*554.00 FL
14	1		*HOOD	Bent	734.00 FL	*734.00 FL
15	1		*HINGE, HOOD, LH	Bent	56.00 FL	*56.00 FL
16	1		*HINGE, HOOD, RH	Bent	56.00 FL	*56.00 FL
17	1		*INSULATOR, HOOD	Not Necessary	177.00 FL	*- FL
18	8		*CLIP, HOOD INSULATOR	Not Necessary	24.00 FL	*- FL
19	1		*LATCH, HOOD	Bent	69.00 FL	*69.00 FL
20	1		*FENDER, FR LH	Not Necessary	497.00 FL	*- FL
21	1		*FENDER, FR RH	Bent	497.00 FL	*497.00 FL
22	1		*SHIELD, FR WHEELHOUSE, LH	Not Necessary	98.00 FL	*- FL
23	1		*SHIELD, FR WHEELHOUSE, RH	Not Necessary	98.00 FL	*- FL
24	14		*CLIP, INNERSHIELD	Not Necessary	56.00 FL	*- FL
25	1		*PANEL ASSY, FR END	Bent	1,055.00 FL	*1,055.00 FL
26	1		*PANEL, HEADLAMP SUPPORT, UPR	Bent	65.00 FL	*65.00 FL
27	2		*PLATE, FR SIDEMEMBER	Not Necessary	94.00 FL	*- FL
28	1		*COVER, ENG ROOM UNDER, FR	Deformed	99.00 FL	*99.00 FL
29	1		*PANEL, AIR GUIDE, LH	Deformed	11.00 FL	*11.00 FL
30	1		*PANEL, AIR GUIDE, RH	Deformed	11.00 FL	*11.00 FL
31	1		*PANEL, AIR GUIDE	Deformed	112.00 FL	*112.00 FL
32	1		*RADIATOR ASSY	Bent	967.00 FL	*967.00 FL
33	1		*TANK ASSY, RADIATOR COND	Deformed	42.00 FL	*42.00 FL
34	1		*FAN, COOLING	Not Necessary	77.00 FL	*- FL
35	1		*SHROUD, COOLING FAN	Not Necessary	130.00 FL	*- FL
36	1		*MOTOR, COOLING FAN	Not Necessary	479.00 FL	*- FL
37	1		*CONDENSER ASSY, A/C REFRIGE	Bent	758.00 FL	*758.00 FL
38	1		*INSULATOR, ENG MOUNTING	Bent	203.00 FL	*203.00 FL
39	1		*ROD ASSY, ENG ROLL STOPPER	Not Necessary	155.00 FL	*- FL
40	1		*INSULATOR, T/M MOUNTING	Bent	209.00 FL	*209.00 FL
41	1		*HEADLAMP ASSY, LH	Cracked	660.00 FL	*660.00 FL
42	1		*HEADLAMP ASSY, RH	Cracked	660.00 FL	*660.00 FL
43	1		*LAMP ASSY, FOG, FR LH	Not Necessary	303.00 FL	*- FL
44	1		*LAMP ASSY, FOG, FR LH	Not Necessary	303.00 FL	*- FL
45	1		*UNPAINTED BODYKITS	Cracked	1,643.00 FN	*1,643.00 F
46	2		*EMBLEM ECO	Necessary	34.00 FS	*34.00 FS
47	1		*LLC 4L	Necessary	26.00 FL	*26.00 FL
48	1		*INSULATOR, ENG MOUNTING (Supplementary)	Repeated	203.00 FL	*- FL
49	1		*INSULATOR, T/M MOUNTING (Supplementary)	Repeated	209.00 FL	*- FL
50	1		*PIPE, A/C CONDENSER OUTLET (Supplementary)	Bent	305.00 FL	*305.00 FL
51	1		*COVER, FR BUMPER (Supplementary)	Deformed	12.00 FL	*12.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$) **13,190.00** **10,033.00**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 23.00/23.00% (S\$)					2,613.49	1,887.38
- Nett Item Discount on N Items 20.00/0.00% (S\$)					328.60	0.00
Total Parts (S\$)					10,247.91	8,145.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT BUMPER BODY KIT, FRT SUPPORT, BONNET, LHF FENDER & RHR FENDER. REPAIR RHF DOOR, RHF A PILLAR, LHF WHEELHOUSE, RHF WHEELHOUSE & FRT CHASSIS LH / RH	New	3,600.00	1,800.00
2	RESPRAY FRT BUMPER, FRT BUMPER BODY KIT, FRT SUPPORT, BONNET, LHF FENDER, LHF WHEELHOUSE, RHF FENDER, RHF WHEELHOUSE, LHF DOOR, RHF DOOR, RHF A PILLAR & FRT CHASSIS LH / RH	New	3,850.00	1,750.00
3	REMOVE & REFIT AC CONDENSER & RADIATOR	New	100.00	100.00
4	TOP UP AIRCON GAS	New	80.00	80.00
5	REMOVE & REFIT ENGINE AND GEARBOX ASSY. RENEW ENGINE & GEARBOX MOUNTING	New	900.00	900.00
6	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	CONDUCT FRT CHASSIS ALIGNMENT-CELLETE BENCH	New	1,000.00	1,000.00
9	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
10	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	80.00
11	REPAIR BOTH WHEEL HOUSING PANEL, REPLACE SUPPORT PANEL (Supplementary)	New	900.00	900.00
12	SPRAY PAINT LH FRONT FENDER, BOTH WHEEL HOUSING, FRONT SUPPORT PANEL, FRONT CHASSIS & RH FRONT A PILLAR (Supplementary)	New	1,400.00	1,400.00
Gross Labour Cost (\$\$)			12,180.00	8,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >