

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20011080/ATD3E2
Date: 25/01/2021

REFERENCE

Insured/Claimant: LOW KOK CHEONG ATTICUS Policy No: 1700069824-02
Date of Loss: 10/10/2020 Nature of Claim: OD Claim No: 2432304266SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT3704K**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN045413
Reg. Date: 26/10/2017 (Man. Year: 2017) Chassis No: WAUZZZF41JA022951
Colour: Black Odometer: 63355 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$98,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 28,900.00 | 13,610.80 | 15,289.20 | 52.90 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 6,022.00 | 3,872.00 | 2,150.00 | 35.70 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 34,922.00 | 17,482.80 | 17,439.20 | 49.94 |
| - Excess (S\$) | 600.00 | 600.00 | 0.00 | 0.00 |
| (S\$) | 34,322.00 | 16,882.80 | 17,439.20 | 50.81 |
| + GST 7.00/7.00% (S\$) | 2,402.54 | 1,181.80 | 1,220.74 | 50.81 |
| Nett Amount (S\$) | 36,724.54 | 18,064.60 | 18,659.94 | 50.81 |

INSPECTION

Date of Assignment: 13/10/2020
Date Inspected: 13/10/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|--------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Deformed | 2,111.00 FS | *1,688.80 FS |
| 2 | 1 | | *FRONT BUMPER FIXING PARTS | Not Necessary | 282.00 FS | *- FS |
| 3 | 2 | | *FRONT BUMPER SECURING STRIP | Not Necessary | 70.00 FS | *- FS |
| 4 | 1 | | *FRONT BUMPER GRILLE -CENTRE | Cracked | 194.00 FS | *154.80 FS |
| 5 | 1 | | *FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE | Not Necessary | 208.00 FS | *- FS |
| 6 | 1 | | *RADIATOR GRILLE | Cracked | 1,799.00 FS | *1,439.20 FS |
| 7 | 1 | | *FRONT BUMPER AIR GUIDE -LH/RH | N/S Cut | 722.00 FS | *288.80 FS |
| 8 | 1 | | *FRONT BUMPER FOAM FILLER PIECE | Cracked | 123.00 FS | *98.40 FS |
| 9 | 1 | | *FRONT BUMPER CARRIER | Bent | 795.00 FS | *635.60 FS |
| 10 | 1 | | *FRONT BUMPER TOP COVER | Not Necessary | 126.00 FS | *- FS |
| 11 | 1 | | *FRONT BUMPER GUIDE SECTION -LH | Not Necessary | 36.00 FS | *- FS |
| 12 | 1 | | *FRONT BUMPER GUIDE SECTION -RH | Not Necessary | 37.00 FS | *- FS |
| 13 | 1 | | *CAUTION SIGN STICKER | Not Necessary | 14.00 FS | *- FS |
| 14 | 1 | | *AIRCON STICKER | Not Necessary | 8.00 FS | *- FS |
| 15 | 1 | | *LOCK CARRIER BRACKET | Cracked | 136.00 FS | *108.40 FS |
| 16 | 2 | | *LOCK CARRIER BRACKET SUPPORT-LH/RH | Not Necessary | 56.00 FS | *- FS |
| 17 | 1 | | *BONNET | Dented | 2,763.00 FS | *2,210.40 FS |
| 18 | 1 | | *BONNET ATTACHMENT PARTS | Not Necessary | 121.00 FS | *- FS |
| 19 | 2 | | *BONNET LID HINGE -LH/RH | Not Necessary | 602.00 FS | *- FS |
| 20 | 1 | | *BONNET IMPACT PROTECTION -CENTRE | Necessary | 27.00 FS | *21.52 FS |
| 21 | 1 | | *BONNET IMPACT PROTECTION -LH | Necessary | 28.00 FS | *21.84 FS |
| 22 | 1 | | *BONNET IMPACT PROTECTION -RH | Necessary | 27.00 FS | *21.52 FS |
| 23 | 2 | | *BONNET STRIKER -LH/RH | Not Necessary | 100.00 FS | *- FS |
| 24 | 2 | | *BONNET LID LOCK | Not Necessary | 423.00 FS | *- FS |
| 25 | 1 | | *BONNET BOWDEN CABLE -INNER | Not Necessary | 57.00 FS | *- FS |
| 26 | 1 | | *BONNET BOWDEN CABLE -OUTER | Not Necessary | 57.00 FS | *- FS |
| 27 | 1 | | *FRONT FENDER -LH | Buckled | 758.00 FS | *606.00 FS |
| 28 | 1 | | *FRONT FENDER ATTACHMENT PARTS | Not Necessary | 200.00 FS | *- FS |
| 29 | 1 | | *FRONT FENDER CLOSING ELEMENT -LH | Not Necessary | 49.00 FS | *- FS |
| 30 | 1 | | *FRONT FENDER BRACKET -LH | Not Necessary | 35.00 FS | *- FS |
| 31 | 1 | | *FRONT FENDER BRACE -LH | Not Necessary | 117.00 FS | *- FS |
| 32 | 1 | | *WHEEL HOUSING LINER -LH | Not Necessary | 237.00 FS | *- FS |
| 33 | 1 | | *WHEEL HOUSING LINER ATTACHMENT PARTS | Not Necessary | 90.00 FS | *- FS |
| 34 | 1 | | *WHEEL SPOILER | Not Necessary | 73.00 FS | *- FS |
| 35 | 1 | | *WHEEL SPOILER TRIM -LH | Not Necessary | 35.00 FS | *- FS |
| 36 | 1 | | *STONE CHIP GUARD -LH | Necessary | 50.00 FS | *39.92 FS |
| 37 | 1 | | *TOP FENDER LEDGE COVER -UPPER | Not Necessary | 31.00 FS | *- FS |
| 38 | 1 | | *TOP FENDER LEDGE COVER -LOWER | Not Necessary | 23.00 FS | *- FS |
| 39 | 1 | | *LED HEADLIGHT -LH/RH | N/S Cracked | 15,386.00 FS | *6,154.40 FS |
| 40 | 2 | | *LIFT CYLINDER -LH/RH | Not Necessary | 416.00 FS | *- FS |
| 41 | 2 | | *RADIATOR AIR GUIDE -LH/RH | Deformed | 56.00 FS | *22.08 FS |
| 42 | 2 | | *RADIATOR AIR GUIDE -LH/RH | Deformed | 24.00 FS | *9.36 FS |
| 43 | 1 | | *RADIATOR AIR GUIDE -UPPER | Not Necessary | 16.00 FS | *- FS |
| 44 | 1 | | *RADIATOR AIR GUIDE -LOWER | Not Necessary | 22.00 FS | *- FS |
| 45 | 1 | | *FRONT NO PLATE | Bent | 60.00 FS | *60.00 FS |
| 46 | 1 | | *SUNDRIES | Necessary | 300.00 FS | *29.76 FS |

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 28,900.00 13,610.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|---------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY | New | 280.00 | 280.00 |
| 2 | TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES | New | 700.00 | 250.00 |
| 3 | TO DISMANTLE AND RENEW FRONT BUMPER ,BONNET,LHS FRONT FENDER AND BOTH HEADLIGHTS ,RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED | New | 2,000.00 | 1,500.00 |
| 4 | TO RESPRAY FRONT BUMPER ,LHS FRONT FENDER ,BONNET ,HINGES AND LHS UPPER A-PILLAR | New | 2,850.00 | 1,650.00 |
| 5 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| | | | Gross Labour Cost (\$\$) | 3,872.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >