



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 5579Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BONNET	DENTED	1,170.00	1,170.00
1	FRONT R/H HEADLAMP	CRACKED	862.40	862.40
1	FRONT R/H HEADLAMP BRACKET	NOT NECESSARY	95.00	-
1	FRONT GRILLE	CRACKED	484.70	484.70
1	FRONT GRILLE EMBLEM	NECESSARY	115.70	115.70
1	FRONT BUMPER (TOP)	DEFORMED	864.20	864.20
8	FRONT BUMPER CLIP	NECESSARY	30.00	30.00
1	FRONT BUMPER (LOWER)	CRACKED	685.00	685.00
2	FRONT BUMPER SIDE RETAINER	NECESSARY	150.00	150.00
1	FRONT BUMPER RH SIDE GARNISH	CUT	188.20	188.20
1	FRONT BUMPER SPONGE	CRACKED	117.60	117.60
1	FRONT BUMPER REINFORCEMENT BEAM	NOT NECESSARY	752.00	-
1	FRONT NO. PLATE GARNISH	CRACKED	95.00	95.00
1	REAR L/H BOOTLID	DENTED	2,355.50	2,355.50
2	REAR L/H BOOTLID HINGE	NOT NECESSARY	232.60	-
4	REAR BOOTLID EMBLEM	NECESSARY	280.00	280.00
1	REAR L/H BOOTLID LOCK	DAMAGED	244.60	244.60
1	REAR L/H BOOTLID HANDLE GARNISH	CRACKED	462.90	462.90
1	REAR L/H BOOTLID INNER TRIMBOARD	CRACKED	288.70	288.70
1	REAR BOOTLID RUBBER	CUT	286.40	286.40
1	REAR L/H TAILLAMP	CUT	422.10	422.10
1	REAR END PANEL	DENTED	430.00	430.00
1	REAR END PANEL GARNISH	DEFORMED	347.70	347.70
1	REAR BUMPER	DISTORTED	734.30	734.30
8	REAR BUMPER CLIP	NECESSARY	30.00	30.00
2	REAR BUMPER SIDE RETAINER	NECESSARY	150.80	150.80
2	REAR BUMPER REFLECTOR	N/S CUT	234.00	117.00
1	REAR BUMPER REINFORCEMENT BEAM	BENT	520.90	520.90
1	REAR L/H WINDSCREEN MOULDING	NECESSARY	60.00	60.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-	-1,149.37
			12,690.30	10,344.33
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NO. PLATE (SN)	BENT	26.00	26.00
1	FRONT NO. PLATE COVER (SN)	DEFORMED	26.00	26.00
1	REAR 70KM/H STICKER (SN)	NECESSARY	15.00	15.00
1	REAR 6 PAX STICKER (SN)	NECESSARY	15.00	15.00
1	REAR REVERSE CAMERA (SN)	DAMAGED	380.00	380.00
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	200.00	200.00
1	REAR L/H WINDSCREEN INNER SEAL (SN)	NECESSARY	26.00	26.00
1	REAR L/H WINDSCREEN SEALANT (SN)	NECESSARY	45.00	45.00
1	REAR NO. PLATE (SN)	NOT NECESSARY	26.00	-
1	REAR NO. PLATE COVER (SN)	NOT NECESSARY	26.00	-
			785.00	733.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	50.00
	TO SPRAY PAINTING.		1,600.00	1,400.00
	TO REMOVE & REFIX REAR WINDSCREEN.		150.00	80.00
	TO MEASURE, DRILL THE REPLACED REAR BUMPER, POSITION & REINSTALL REAR REVERSE SENSOR, CONTROL UNIT, CAMERA & TEST FOR FUNCTIONING.		80.00	80.00
	TO SUPPLY AND INSTALL FOR FIAT DOGLO VAN STICKER, 2PC REAR BOOTLID, 1PC REAR LH FENDER, REAR BUMPER, 1PC FRONT BUMPER, 1PC FRONT RH FENDER & BONNET. LABOUR CHARGE FOR REMOVAL AND CLEANING OF STAINS, STICKER CODE ORACAL 970ra. TO SUPPLY ART WORK DESIGN. INVOICE NUMBER : 5412.		1,200.00	1,200.00
	LABOUR CHARGE FOR PANEL BEATING, REMOVING AL DAMAGE PARTS & REPLACING OF THE NEW PARTS ETC.		1,200.00	1,200.00
			4,280.00	4,010.00
<b>GRAND TOTAL</b>			<b>17,755.30</b>	<b>15,087.33</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>12,050.00</b>
---	--	--	------------------

Report Ref No. CS/TP20011082/Avd3e2

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**