

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20011083/AGA3Q2

Date: 09/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : GBA4652M	Insured Vehicle No :	SHA7142C
Date of Loss: 08/10/2020	Nature of Claim: TP	Claim No: MCT20100123

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA4652M	
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Engine No: 1KD1648677
Reg. Date:	17/07/2007 (Man. Year: 2007)	Chassis No: JTFAT35Y103001045
Colour:	White	Odometer: 613749 km
Engine Capacity:	2982 cc	
Market Value/New Car Price:	N/A	
Sum Insured (\$\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	165 R12C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,769.10	2,986.85	7,782.25	72.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,390.00	960.00	40.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,119.10	4,376.85	8,742.25	66.64
Approved Total (Overridden) (\$\$)		3,500.00		
Nett Amount (\$\$)	13,119.10	3,500.00	9,619.10	73.32
+ Loss of Use (5.0 x S\$60.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,807.45		

INSPECTION

Date of Assignment:	13/10/2020	
Date Inspected:	13/10/2020 Inspected At:	Hua Meng Spray Painting Workshop (HQ)
		No 1 Kaki Bukit Avenue 6, #01-61
		Autobay@Kaki Bukit
		Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Feb 2021)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA4652M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	N/S Cracked	682.80 FL	*255.00 FL
2	1		*TAILGATE PANEL	N/S Bent	241.60 FL	*120.80 FL
3	1		*REAR NUMBER PLATE BRACKET	Not Necessary	198.40 FL	*- FL
4	1		*REAR CHASSIS NUMBER (LOCAL REPAIR)	N/S Bent	2,587.50 FS	*500.00 FS
5	1		*REAR NUMBER PLATE	Not Necessary	60.00 FS	*- FS
6	1		*REAR STEP PANEL	Bent	632.50 FS	*450.00 FS
7	1		*REAR STEP PANEL ALUMINIUM PLATE	Bent	230.00 FS	*180.00 FS
8	1		*REAR CAMERA	Damaged	552.00 FS	*380.00 FS
9	2		*REAR CHASSIS NUMBER RUBBER PAD	Cut	345.00 FS	*345.00 FS
10	1		*REAR BOX REFRIGERATOR LOWER STAINLESS STEEL FRAME	Dented	1,092.50 FS	*850.00 FS
11	1		*REAR BOX REFRIGERATOR BOX RUBBER SEAL	Not Necessary	287.50 FS	*- FS
12	2		*REAR BOX REFRIGERATOR DOOR	Repair	4,140.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,049.80	3,080.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	280.70	93.95
Total Parts (\$\$)	10,769.10	2,986.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	REMOVE ,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,400.00	700.00
3	RESPRAY PAINTING	New	800.00	600.00
4	TUFF KOTE	New	100.00	60.00
Gross Labour Cost (\$\$)			2,350.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >