



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2201906

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 04/04/2022
Reference CC4/FCI20011084/Kea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. YN 4023M
Insured Veh. SHD 6980R
Claim No. D20002552MFSH
Policy No. D-20094922MFSH
Accident Date 24/06/2020
Inspection Date 13/10/2020

Description	Total
Survey Inspection	259.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	259.00
GST (7%)	18.13
Grand Total	277.13

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20011084/Kea3q2 Date: 04/04/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6980R	Veh. Inspected	YN 4023M	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20002552MFSH	Excess (\$)	0.00	
Assign From	SANGHILAN VIC ALPEH SUMAGANG	Assign Date	13/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi canter (M)	c.c	2977	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	FE83BEA21093	Colour	WHITE	
Odometer	341735 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	700 R16X8	WEST LAKE	9 mm	
L/H Front Tyre	700 R16X8	WEST LAKE	9 mm	
R/H Rear Tyre	185 R14X8 (D)	WEST LAKE	2/2 mm	
L/H Rear Tyre	185 R14X8 (D)	WEST LAKE	2/2 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	24/06/2020	Inspection Date	13/10/2020	
Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 4023M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	961.95	961.95
1	FRONT SIGNAL LAMP -LH	BROKEN	206.10	206.10
1	FRONT SIDE LAMP -LH	BROKEN	139.05	139.05
1	HEADLAMP -LH	NOT NECESSARY	721.30	-
1	HEADLAMP LOWER RUBBER LID	MISSING	15.00	15.00
1	FRONT DOOR	BENT	1,910.05	1,910.05
2	FRONT DOOR HINGES (TOP/LOWER) @\$171.60	TO REPAIR SEE LABOUR	343.20	-
1	FRONT DOOR CHECKER	SERVICEABLE	58.79	-
1	FRONT DOOR STEP GARNISH	SERVICEABLE	415.44	-
1	FRONT DOOR REGULATOR }	NOT NECESSARY	1,065.87	-
1	FRONT DOOR REGULATOR MOTOR }		-	-
1	FRONT DOOR WEATHERSTRIP	SERVICEABLE	236.00	-
	LESS 25% DISCOUNT		-1,518.19	-808.04
			4,554.56	2,424.11
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR COMPANY ADVERTISEMENT STICKER (SN)	NECESSARY	180.00	120.00
			180.00	120.00
	<u>LABOUR</u>			
	TO REMOVE CUT OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR HINGES (TOP/LOWER) .		250.00	250.00
	TO REMOVE DOOR'S FITTINGS.		80.00	60.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		600.00	400.00
	TO FOCUS HEADLAMPS .TO CHECK REAR WIRING AND LIGHTING OPERATION		30.00	20.00
			960.00	730.00
	GRAND TOTAL		5,694.56	3,274.11



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,600.00
---	--	--	----------

Report Ref No. CC4/FCI20011084/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YN 4023M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YN 4023M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

