

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20011088/T1VD3Q2**Date:** 10/11/2020REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00018532000

Claimant Vehicle No : FBK5709A **Insured Vehicle No :** GBJ4807L

Date of Loss: 23/09/2020 Nature of Claim: TP Claim No: SNM20D203618/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK5709A**

Make & Model: YAMAHA FZ150, 150cc Engine No: G3E3E0001621

Reg. Date: 27/10/2015 (Man. Year: 2015) Chassis No: ME1RG1612F2001447

Colour: Red Odometer: 0 km

Engine Capacity: 149 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80 R17 Rear Tyre Size: 120/70 R17

Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,071.00	963.00	108.00	10.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	410.00	195.00	215.00	52.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,481.00	1,158.00	323.00	21.81
Approved Total (Overridden) (S\$)		800.00		
(S\$)	1,481.00	800.00	681.00	45.98
+ GST 7.00/7.00% (S\$)	103.67	56.00	47.67	45.98
Nett Amount (S\$)	1,584.67	856.00	728.67	45.98

INSPECTION

Date of Assignment: 14/10/2020

Date Inspected: 16/10/2020 Inspected At:

Southern Motor (HQ)
BLK 1006 BUKIT MERAH LANE 2,
#01-10
Singapore 159762

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Nov 2020)	
Parts:	N/A	YAMAHA FZ150 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK5709A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Cracked	55.00 FN	*55.00 FN
2	1		*HANDLE BAR	Not Necessary	65.00 FN	*- FN
3	1		*FUEK TANK COVER	Cut	180.00 FN	*180.00 FN
4	1		*SIDE BOX	Cracked	110.00 FN	*110.00 FN
5	1		*CENTRE FAIRING	N/S Not Necessary /O/S Cut	110.00 FN	*55.00 FN
6	1		*HANDLE BALANCER	Cut	25.00 FN	*25.00 FN
7	1		*BRAKE LEVER	Cut	20.00 FN	*20.00 FN
8	1		*SET EXHAUST PIPE / COVER	Cracked	480.00 FN	*480.00 FN
9	1		*FRONT FOOTREST	Dented	35.00 FN	*35.00 FN
10	1		*HEADLAMP COVER	Cut	110.00 FN	*110.00 FN

F=Franchise part. N=NettItemDisc.

Sub Total (\$\$)	1,190.00	1,070.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	119.00	107.00
Total Parts (\$\$)	1,071.00	963.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT	New	30.00	30.00
2	IU	New	165.00	0.00
3	ALIGNMENT FORK	New	65.00	65.00
4	LABOR	New	150.00	100.00
			Gross Labour Cost (\$\$)	195.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >