

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI20011089/UQF3Q2**Date:** 02/11/2020REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00060222004		
<b>Claimant Vehicle No :</b>	SLM4832D	<b>Insured Vehicle No :</b>	GBE242T		
Date of Loss:	10/10/2020	Nature of Claim:	TP	Claim No:	SNM20D203826/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLM4832D</b>			
Make & Model:	MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A)	Engine No:	4A92CN2338	
Reg. Date:	31/03/2017 (Man. Year: 2016)	Chassis No:	JMYSRCY1AGU006402	
Colour:	Black	Odometer:	57440 km	
Engine Capacity:	1590 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 ZR18	Rear Tyre Size:	225/40 ZR18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,786.78	7,471.20	5,315.58	41.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,320.00	1,920.00	1,400.00	42.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,106.78</b>	<b>9,391.20</b>	<b>6,715.58</b>	<b>41.69</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>16,106.78</b>	<b>7,500.00</b>	<b>8,606.78</b>	<b>53.44</b>

INSPECTION

Date of Assignment:	13/10/2020	
Date Inspected:	13/10/2020 Inspected At:	Ping Motor Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-25 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	6.0 days	

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2020)
<b>Parts:</b> 143	MITSUBISHI LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLM4832D)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Badly Dented	980.50 FL	*980.50 FL
2	1		*FRONT DOOR WINDOW GLASS OUTER MOULDING LH	Bent/Necessary	208.90 FL	*145.50 FL
3	1		*SET FRONT DOOR BLACK TAPE LH	Necessary	131.60 FL	*80.00 FL
4	1		*FRONT DOOR QUARTER GARNISH LH	Not Necessary	68.00 FL	*- FL
5	2		*FRONT DOOR HINGE U/L (LH)	Twisted	240.60 FL	*240.60 FL
6	1		*FRONT CHECKER LH	Twisted	98.40 FL	*98.40 FL
7	1		*FRONT DOOR WEATHER STRIP LH	Necessary	145.80 FL	*145.80 FL
8	1		*FRONT DOOR MECHANISM LOCK LH	Not Necessary	228.60 FL	*- FL
9	1		*FRONT DOOR LOCK STRIKER LH	Not Necessary	55.00 FL	*- FL
10	1		*FRONT DOOR WINDOW GLASS REGULATOR LH	Bent	258.10 FL	*258.10 FL
11	1		*FRONT DOOR WINDOW GLASS REGULATOR MOTOR LH	Not Necessary	189.40 FL	*- FL
12	1		*FRONT DOOR INNER TRIM BOARD LH	Torn	780.20 FL	*540.00 FL
13	1		*SET FRONT DOOR INNER TRIM BOARD CLIP LH	Necessary	55.00 FL	*40.00 FL
14	1		*FRONT DOOR SIDE MIRROR GLASS LH	Broken	172.60 FL	*172.60 FL
15	1		*FRONT DOOR SIDE MIRROR LH	Broken	586.20 FL	*586.20 FL
16	1		*FRONT FENDER LH	Dented/Bent	482.50 FL	*482.50 FL
17	1		*FRONT FENDER INNER SHIELD LH	Torn	157.30 FL	*157.30 FL
18	1		*SET FRONT FENDER INNER SHIELD CLIP LH	Necessary	22.00 FL	*22.00 FL
19	1		*FRONT FENDER SIGNAL LH	Not Necessary	63.00 FL	*- FL
20	1		*FRONT FENDER EMBLEM	Necessary	68.00 FL	*68.00 FL
21	1		*FRONT HEADLAMP LH	Cracked	932.00 FL	*932.00 FL
22	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	45.00 FL	*- FL
23	1		*FRONT PILLAR (LH)	Repair	1,258.40 FL	*- FL
24	1		*FRONT WINDSCREEN MOULDING	Not Necessary	128.60 FL	*- FL
25	1		*FRONT LOWER ARM LH	Bent	365.90 FL	*365.90 FL
26	1		*FRONT KNUCKLE LH	Bent	420.60 FL	*420.60 FL
27	1		*FRONT KNUCKLE BEARING LH	Necessary	132.00 FL	*132.00 FL
28	1		*FRONT CUSTOMIZED BUMPER	Cut/Torn	1,600.00 FS	*1,400.00 FS
29	1		*FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
30	1		*FRONT DOOR VISOR	Necessary	150.00 FS	*60.00 FS
31	1		*FRONT SPORT RIM LH	Bent	380.00 FS	*350.00 FS
32	1		*FRONT TYRE LH	Not Necessary	330.00 FS	*- FS
33	1		*FRONT SHOCK ABSORBER LH	Not Necessary	500.00 FS	*- FS
34	1		*FRONT SIDE SKIRT LH	Torn	350.00 FS	*350.00 FS
35	1		*FRONT BONNET (CARBON FIBRE)	Not Necessary	2,000.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** 13,614.20    8,058.00  
**- List Item Discount on L Items 10.00/10.00% (\$\$)** 827.42    586.80

**Total Parts (\$\$)** 12,786.78    7,471.20

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & TRANSFER FRONT DOOR COMPONENTS }	New	150.00	60.00
2	TO TRANSFER FRONT DOOR GLASS,REGULATOR GEAR,MOTOR,RAILING CHANNEL,TRIM BOARD,MECHANISM LOCK AND HANDLE }	New	120.00	0.00
3	TO RUSTPROOF AFFECTED AREAS	New	100.00	60.00
4	TO REMOVE,CHECK & REPLACE FRONT UNDERCARRIAGE PARTS	New	250.00	120.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	100.00
6	TO REMOVE,REINSTALL FRONT WINDSCREEN	New	150.00	0.00
7	TO STRAIGHTEN,REPAIR,REALIGN ON FRONT & REAR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,200.00	600.00
8	TO SPRAY PAINTING ON AFFECTED AREA	New	1,200.00	980.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,320.00</b>	<b>1,920.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >