

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20011092/QQD3E2
Date: 21/10/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100493627
Claimant Vehicle No :	SLC8052P	Insured Vehicle No :	GBF5547B
Date of Loss:	10/10/2020	Nature of Claim:	TP
		Claim No:	8835646821SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC8052P	Engine No:	L15B3535902
Make & Model:	HONDA SHUTTLE, 1.5 G (A)	Chassis No:	GK81005060
Reg. Date:	26/05/2016 (Man. Year: 2016)	Odometer:	60940 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	13/10/2020	
Date Inspected:	14/10/2020	Inspected At:
		Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: OI SUN PIN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Dented	0.00 F	*- F
2	1		*FRT LH DOOR WING MIRROR	Missing	0.00 F	*- F
3	1		*FRT LH DOOR GARNISH GLASS	Cut	0.00 F	*- F
4	1		*FRT LH DOOR GLASS OUTER MOULDING	Cut	0.00 F	*- F
5	1		*FRT LH DOOR GLASS	Broken	0.00 F	*- F
6	1		*FRT LH DOOR RUBBER	Necessary	0.00 F	*- F
7	1		*FRT LH DOOR LOCK	Jammed	0.00 F	*- F
8	1		*FRT LH DOOR SWITCH	Scratched	0.00 F	*- F
9	1		*FRT LH DOOR HANDLE	Crumpled	0.00 F	*- F
10	1		*ROCKER PANEL GARNISH LH	Repair	0.00 F	*- F
11	1		*FRT BUMPER	Repair	0.00 F	*- F
12	1		*FRT LH FENDER	Crumpled	0.00 F	*- F
13	1		*REAR LH DOOR	Dented	0.00 F	*- F
14	1		*REAR LH DOOR PROTECTOR RUBBER	Cut	0.00 F	*- F
15	1		*REAR LH DOOR RUBBER	Necessary	0.00 F	*- F
16	1		*REAR LH FENDER	Repair	0.00 F	*- F
17	1		*FRONT LH HEADLAMP	Scratched	0.00 F	*- F
18	1		*FRONT LH WHEEL RIM	Cut	0.00 F	*- F
19	1		*REAR LH WHEEL RIM	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >