

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20011094/T1TF3E2

Date: 19/11/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001408921

Claimant Vehicle No : SMU6017Z

Insured Vehicle No : SJV5683L

Date of Loss: 10/10/2020

Nature of Claim: TP

Claim No: 248654

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU6017Z**

Make & Model: MASERATI GHIBLI V6, 3.0 (A)

Engine No: M15746D057226

Reg. Date: 01/09/2017 (Man. Year: 2017)

Chassis No: ZAMTS57C001251213

Colour: Blue

Odometer: 72977 km

Engine Capacity: 2987 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18

Rear Tyre Size: 225/50 R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	52,177.08	14,436.41	37,740.67	72.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,550.00	2,460.00	4,090.00	62.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	58,727.08	16,896.41	41,830.67	71.23
Approved Total (Overridden) (S\$)		13,050.00		
Nett Amount (S\$)	58,727.08	13,050.00	45,677.08	77.78

INSPECTION

Date of Assignment: 15/10/2020

Date Inspected: 15/10/2020 Inspected At:

Perpendicular Pte Ltd (HQ)
60 JALAN LAM HUAT SINGAPORE, #03-27,
CARROS CENTRE
Singapore 737869

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2021)
Parts:	143	MASERATI GHIBLI V6 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU6017Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH MUFFLER	Repair	5,163.00 F	*- F
2	1		*FLEXIBLE PAD	Not Necessary	47.50 F	*- F
3	1		*RH REAR SILENCER SUPPORT	Deformed	93.35 F	*93.35 F
4	1		*RH REAR SILENCER SUPPORT SCREWS	Not Necessary	11.15 F	*- F
5	1		*SPACER	Not Necessary	52.45 F	*- F
6	1		*SPACER SCREWS	Not Necessary	7.40 F	*- F
7	1		*ADBLUE TANK	Not Necessary	5,741.20 F	*- F
8	1		*LH SILENCER HEAT SHIELD	Not Necessary	75.60 F	*- F
9	1		*REAR NOX SENSOR	Not Necessary	2,007.35 F	*- F
10	1		*COLLAR	Not Necessary	27.50 F	*- F
11	1		*ADBLUE DOSER MODULE	Not Necessary	574.15 F	*- F
12	1		*ADBLUE DELIVERY PIPE	Not Necessary	603.05 F	*- F
13	1		*EXHAUST GAS TEMPERATURE SENSOR	Not Necessary	355.21 F	*- F
14	1		*ADBLUE HEATER CONTROL UNIT	Not Necessary	479.15 F	*- F
15	1		*BRAKET	Not Necessary	16.50 F	*- F
16	1		*SHIELD	Not Necessary	78.10 F	*- F
17	1		*FRONT NOX SENSOR	Not Necessary	2,544.30 F	*- F
18	1		*BRACKET	Not Necessary	47.50 F	*- F
19	1		*SCREW	Not Necessary	11.15 F	*- F
20	1		*SCREW (M6X16)	Not Necessary	3.75 F	*- F
21	1		*SCREW	Not Necessary	11.15 F	*- F
22	1		*NUT	Not Necessary	11.15 F	*- F
23	1		*L.H. STRAP	Not Necessary	51.25 F	*- F
24	1		*R.H. STRAP	Not Necessary	47.50 F	*- F
25	1		*PAD	Not Necessary	262.70 F	*- F
26	1		*PLUG	Not Necessary	213.55 F	*- F
27	1		*FILTER	Not Necessary	29.35 F	*- F
28	1		*RIVET	Not Necessary	14.90 F	*- F
29	1		*CLIP	Not Necessary	11.15 F	*- F
30	1		*REAR CHASSIS ASSEMBLY	Not Necessary	4,584.70 F	*- F
31	1		*SCREW (M14x145)	Not Necessary	62.40 F	*- F
32	1		*SCREW	Not Necessary	80.55 F	*- F
33	1		*CLIP	Not Necessary	37.20 F	*- F
34	1		*CLIP	Not Necessary	5.60 F	*- F
35	1		*LH BRACKET	Not Necessary	20.25 F	*- F
36	1		*RH BRACKET	Not Necessary	20.25 F	*- F
37	1		*SCREW (M10x21.5)	Not Necessary	22.30 F	*- F
38	1		*SCREW	Not Necessary	22.30 F	*- F
39	1		*RH TAILLIGHT FIXED SIDE	Cracked	1,094.55 F	*1,094.55 F
40	1		*LH TAILLIGHT FIXED SIDE	Cracked	1,094.55 F	*1,094.55 F
41	1		*SUPPLEMENTARY STOP LIGHT	Not Necessary	226.35 F	*- F
42	1		*RH TAILLIGHT MOBILE SIDE	Not Necessary	912.80 F	*- F
43	1		*LH TAILLIGHT MOBILE SIDE	Not Necessary	912.80 F	*- F
44	1		*RUBBER	Not Necessary	7.40 F	*- F
45	1		*SCREW (M6x21)	Not Necessary	27.90 F	*- F
46	1		*LH REFLECTOR	Not Necessary	84.30 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*RH REFLECTOR	Cut	84.30 F	*84.30 F
48	1		*R.H. CAP FOR SCREW	Not Necessary	16.50 F	*- F
49	1		*L.H. CAP FOR SCREW	Not Necessary	16.50 F	*- F
50	1		*BUSHING	Not Necessary	11.15 F	*- F
51	1		*SCREW (M6x16)	Not Necessary	14.87 F	*- F
52	1		*RIVET	Not Necessary	14.90 F	*- F
53	1		*LH BODY SIDE FRAME ASSEMBLY	Not Necessary	1,643.90 F	*- F
54	1		*RH BODY SIDE FRAME ASSEMBLY	Not Necessary	1,643.90 F	*- F
55	1		*UPPER LH HEADLIGHT HOUSING GUIDE	Not Necessary	164.40 F	*- F
56	1		*UPPER RH HEADLIGHT HOUSING GUIDE	Not Necessary	165.65 F	*- F
57	1		*LOWER LH HEADLIGHT HOUSING GUIDE	Not Necessary	140.40 F	*- F
58	1		*LOWER RH HEADLIGHT HOUSING GUIDE	Not Necessary	140.40 F	*- F
59	1		*REAR WINDOW CROSS MEMBER	Not Necessary	194.95 F	*- F
60	1		*REAR REINFORCEMENT	Not Necessary	1,090.40 F	*- F
61	1		*LOWER REAR GUARD ASSEMBLY	Bent	1,090.40 F	*1,090.40 F
62	1		*LH REAR SIDE LOWER COVER ASSEMBLY	Not Necessary	178.05 F	*- F
63	1		*RH REAR SIDE LOWER COVER ASSEMBLY	Not Necessary	178.05 F	*- F
64	1		*REAR BUMPER	Deformed	2,916.10 F	*2,916.10 F
65	1		*REAR BUMPER SHOCK ABSORBER	Missing	140.85 F	*140.85 F
66	1		*UNDER TAILLIGHT RH BRACKET	Not Necessary	45.85 F	*- F
67	1		*UPPER CENTRAL BRACKET	Deformed	122.30 F	*122.30 F
68	1		*UNDER-TAILLIGHT LH BRACKET	Not Necessary	45.85 F	*- F
69	1		*GASKET	Not Necessary	22.30 F	*- F
70	1		*RH BUMPER MOUNTING BRACKET	Deformed	78.50 F	*78.50 F
71	1		*LH BUMPER MOUNTING BRACKET	Deformed	78.50 F	*78.50 F
72	1		*SCREW	Necessary	22.30 F	*22.30 F
73	1		*SCREW (10x16)	Necessary	7.45 F	*7.45 F
74	1		*LEFT REAR BUMPER LOWER TRIM	Not Necessary	532.85 F	*- F
75	1		*FASTENER BUTTON	Not Necessary	15.90 F	*- F
76	1		*CENTRAL LOWER TRIM	Deformed	553.46 F	*553.46 F
77	1		*RIGHT REAR BUMPER LOWER TRIM	Not Necessary	532.80 F	*- F
78	1		*SCREW (10x16)	Necessary	14.90 F	*14.90 F
79	1		*SCREW (10x16)	Not Necessary	7.45 F	*- F
80	1		*RIVET	Necessary	55.80 F	*55.80 F
81	1		*RIVET	Not Necessary	14.90 F	*- F
82	1		*PARKING SENSOR	Not Working	1,485.30 F	*1,485.30 F
83	1		*REAR BUMPER PARKING SENSOR BRIDLE	Not Necessary	137.55 F	*- F
84	1		*REAR BUMPER PARKING SENSOR BRIDLE	Not Necessary	254.45 F	*- F
85	1		*RING	Necessary	58.65 F	*58.65 F
86	1		*EXTERNAL LH PARKING SENSOR SLEEVE	Necessary	95.00 F	*95.00 F
87	1		*EXTERNAL RH PARKING SENSOR SLEEVE	Necessary	95.00 F	*95.00 F
88	1		*INTERNAL LH PARKING SENSOR SLEEVE	Necessary	95.00 F	*95.00 F
89	1		*INTERNAL RH PARKING SENSOR SLEEVE	Necessary	95.00 F	*95.00 F
90	1		*CLIP	Not Necessary	279.00 F	*- F
91	1		*SCREW (M6x16)	Not Necessary	3.75 F	*- F
92	1		*LIGHT BAR WITHOUT REAR PARKING CAMERA	Not Necessary	627.33 F	*- F
93	1		*MICROSWITCH REPLACEMENT KIT	Not Necessary	304.85 F	*- F
94	1		*FASTENER BUTTON	Not Necessary	122.30 F	*- F
95	1		*MASERATI LOGO EMBLEM	Necessary	142.45 F	*142.45 F
96	1		*LOGO ON BOOT LID	Necessary	142.45 F	*142.45 F
97	1		*FASTENER BUTTON	Not Necessary	3.80 F	*- F
98	1		*BOOT LID	Bent	3,271.25 F	*3,271.25 F
99	1		*REAR LEFT BOOT LID HINGE	Repair	323.00 F	*- F
100	1		*REAR RIGHT BOOT LID HINGE	Repair	323.00 F	*- F
101	1		*LH HINGE COVER	Not Necessary	46.30 F	*- F
102	1		*RH HINGE COVER	Not Necessary	46.30 F	*- F
103	1		*SCREW	Not Necessary	44.65 F	*- F
104	1		*BOOT LID SPRING	Not Necessary	111.55 F	*- F
105	1		*GASKET	Torn	368.45 F	*368.45 F
106	1		*BOOT LID COVER	Torn	390.35 F	*390.35 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	1		*ANTIVIBRATING PAD	Not Necessary	14.90 F	*- F
108	1		*NUT	Not Necessary	15.20 F	*- F
109	1		*FASTENER BUTTON (6.5x18)	Not Necessary	169.15 F	*- F
110	1		*BLOCK	Not Necessary	47.50 F	*- F
111	1		*PAD	Not Necessary	73.11 F	*- F
112	1		*RUBBER DAMPER	Not Necessary	1.90 F	*- F
113	1		*RIVET	Not Necessary	22.30 F	*- F
114	1		*SIDE PLUG	Not Necessary	3.80 F	*- F
115	1		*PLUG	Not Necessary	5.60 F	*- F
116	1		*LH DOOR	Not Necessary	46.30 F	*- F
117	1		*RH DOOR	Not Necessary	46.30 F	*- F
118	1		*LIFTGATE OPENING SENSOR	Not Necessary	665.00 F	*- F
119	1		*SCREW	Not Necessary	22.30 F	*- F
120	1		*REAR BONNET OPENING SENSOR CABLE	Not Necessary	43.40 F	*- F
121	1		*SCREW	Not Necessary	33.50 F	*- F
122	1		*CLIP	Not Necessary	9.30 F	*- F
123	1		*REAR BONNET COMPLETE ACTUATOR	Not Necessary	1,152.40 F	*- F
124	1		*CONTROL PANEL REAR BONNET CL	Not Necessary	123.50 F	*- F
125	1		*BALL PIN	Not Necessary	5.60 F	*- F
126	1		*BALL PIN	Not Necessary	5.60 F	*- F
127	1		*BALL PIN	Not Necessary	18.40 F	*- F
128	1		*LH BRACKET	Not Necessary	78.50 F	*- F
129	1		*REAR BRACKET	Not Necessary	73.15 F	*- F
130	1		*TRIM PLATE	Not Necessary	17.80 F	*- F
131	1		*LUGGAGE COMPARTMENT LOCK	Bent	147.10 F	*147.10 F
132	1		*BOOT LID STRIKER	Repair	27.50 F	*- F
133	1		*SCREW	Not Necessary	33.10 F	*- F
134	1		*SCREW	Necessary	33.10 F	*33.10 F
135	1		*REAR CROSS MEMBER ASSEMBLY	Bent	570.00 F	*570.00 F

F=Franchise part.

Total Parts (S\$) 52,177.08 14,436.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SILENCER	New	50.00	0.00
2	ADBLUE SYSTEM	New	350.00	100.00
3	REAR CHASSIS	New	800.00	0.00
4	BODYWORK AND REAR OUTER TRIM PANELS	New	350.00	60.00
5	REAR BUMPER AND PARKING SENSOR	New	120.00	40.00
6	REAR LID	New	80.00	60.00
7	BODYWORK	New	2,000.00	1,000.00
8	BODY PAINTWORK	New	2,000.00	1,000.00
9	PROGRAMMING AND DIAGNOSIS	New	800.00	200.00
Gross Labour Cost (\$)			6,550.00	2,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >