Insurance Loss Adjusters and Licensed Appraiser Regn. 652868584L Blk 131 Rivervale Street #05-872 S'pore 540131 Tel:65528323 Fax:64574321

Our ref: PS/002/06/19 Date: 25th June 2019

Mr Naung Latt Maw c/o 160 Sin Ming Drive #02-17 Sin Ming Auto City Singapore 575722

Dear Sir,

Re: THIRD PARTY CLAIM

We refer to your instruction to appraise the vehicle SJR 5318 M on 03rd June 2019.

A static inspection was conducted during our survey and our report is enclosed for your perusal. The estimated repair cost submitted by **Messrs. Yee Auto Service** for \$28,789.48 as per our attached schedule have been inspected thoroughly each and every item and revised by us against the actual damages found on the vehicle which have been recommended by us accordingly.

The repairer has agreed to undertake repairs at our revised amount of \$16,100.00 lump sum corresponding to supply of parts, labour charges and spray-painting. However, we have not given instruction to authorize the repairs.

Under normal circumstances, the estimated period of repairs would be **NINE** (9) days. Photographs of the damaged vehicle taken by us during our inspection are enclosed.

We are reverting the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services.

Yours faithfully,

PRESTIGE APPRAISER SERVICES

LOUIS S C'NG CAE AMIMI Dip. MTM. Automotive Engineer Licensed Appraiser

Encl.

#### VEHICLE INSPECTION REPORT

To: Mr Naung Latt Maw

c/o 160 Sin Ming Drive #02-17 Sin Ming Auto City

Singapore 575722

Date

: 25th June 2019 : PS/002/06/19

Our Ref

Policy No Sum Insured

Excess

: T/P Claim

Assigned By

: Mr Naung Latt Maw Assignment Date : 03rd June 2019

Accident Date Inspection Date Workshop Name

Survey Conducted At

: 01st June 2019 : 03rd June 2019 : Yee Auto Service : 160 Sin Ming Drive

#02-17 Sin Ming Auto City

Singapore 575722

PARTICULARS OF VEHICLE

Registration No Make/Model

: SJR 5318 M : Toyota Camry

: Motorcar Type Of Body Year Of Manu./Regn. : 2009

Colour

: Pearl White

Mileage

142023km HIDDEN

Engine No Chassis No : MR053BK4107046504

Passenger Cap.

: 4 Passengers

Others

CONDITION OF TYRES

R/H SIDE

L/H SIDE

Front Tyre Rear Tyre

: 6mm 215/60R16 Dunlop : 6mm 215/60R16 Dunlop 6mm 215/60R16 Dunlop 6mm 215/60R16 Dunlop

The above represent the estimated remaining life of the tyre treads.

PRE-ACCIDENT CONDITION (Static tests only)

Handbrake Footbrake

Serviceable Serviceable

Body Work Paint Work : Good

Steering

Serviceable

Others

: Good : -

POINT OF IMPACT

The vehicle sustained impacts on the front & rear portion.

GENERAL DESCRIPTION OF DAMAGES

Front: The front support panel, bumper assy, fenders, bonnet were dented.

Rear: The rear body panel, bumper assy, floorboard panel, fenders, bootlid were dented/distorted.

For details of damages please refer to schedule attached.

**REMARKS:** 

This survey was conducted strictly without prejudice.

Vehic	le No: SJR 5318 M		Our Ref:		PS/002/06/19	
Qty	Descriptions LIST ITEMS	Conditions		Repairer's Est.		Our Revised.
1	front bumper	dented	\$	1,028.08	\$	1,028.08
1	front bumper beam	dented	Ψ.	598.30	Ψ.	598.30
1	front bumper sponge	damaged		290.00		290.00
2	front bumper bracket	dented		147.00		147.00
2	front bumper side retainer	dented		197.00		197.00
8	front bumper clip	necessary		64.00		64.00
1	front bumper grille	dented		165.20		165.20
1	R/H fog lamp	holder damaged		448.52		448.52
1	L/H fog lamp	holder damaged		448.52		448.52
1	R/H fog lamp garnish	holder damaged		144.20		144.20
1	L/H fog lamp garnish	holder damaged		144.20		144.20
1	bonnet	dented		1,490.30		1,490.30
1	front support panel	dented - repair		762.93		-
1	brace panel	dented		196.83		196.83
1	front griile	holder fractured		638.80		638.80
1	front griile emblem	necessary		87.30		87.30
3	front griile clip	necessary		18.00		18.00
1	R/H headlamp	dented/distorted		1,083.30		1,083.30
1	L/H headlamp	dented/distorted		1,083.30		1,083.30
1	rear bumper	dented		1,159.50		1,159.50
1	rear bumper reinforcement	dented		683.60		683.60
2	rear bumper bracket	dented		237.80		237.80
2	rear bumper side retainer	dented		231.80		231.80
2	rear bumper reflector	holder damaged		331.70		331.70
8	rear bumper clip	necessary		64.00		64.00
1	rear body panel	dented		725.90		725.90
1	rear body panel top garnish	dented		434.00		434.00
4	rear body panel top garnish clip	necessary		51.60		51.60
1	R/H taillamp	holder damaged		855.60		855.60
1	L/H taillamp	holder damaged		855.60		855.60
2	taillamp panel	dented - repair		386.20		-
1	bootlid	dented/distorted		1,251.90		1,251.90
2	boot hinge	dented - repair		343.90		200
1	boot weatherstrip	distorted		295.60		295.60
1	boot top lock	dented		289.60		289.60
1	boot lower lock	dented		135.00		135.00
1	boot emblem ' 2.0 '	necessary		68.90		68.90
1	boot emblem ' LOGO '	necessary		76.00		76.00
1	boot outer garnish	serviceable		569.60		EN Moderning Bernsen
1	R/H boot reflector	stud damaged		554.80		554.80
1	L/H boot reflector	stud damaged		554.80		554.80
1	boot inner garnish	dented/distorted		425.60		425.60
1	spare wheel panel	dented - repair		1,299.50		-
1	exhaust chrome pipe	dented		245.30		245.30
1	exhaust muffler	dented - repair		955.90		-
				22,119.48		17,801.45
		Less 25%		-		4,450.36
		Balance c/f	\$	22,119.48	\$	13,351.09

ੂ Vehicl	Our Ref:	PS/002/06/19			
Qty	Descriptions	Conditions		Repairer's Est.	Our Revised.
	CAIFTTITEM	Balance b/d	\$	22,119.48	\$ 13,351.09
1set	<u>S/NETT ITEM</u> reverse sensor	damaged		500.00	300.00
	Labour Charges & Misc To dismantle & replace damag necessary.	2,800.00	2,400.00		
	To putty, apply primer & spray-paint on the affected portion.			2,500.00	2,200.00
	To apply rust-proofing on repaired, replaced panel.			350.00	280.00
	To remove/refit rear boot compartment garnish to facilitate repairs.			180.00	150.00
	To remove/renew exhaust mut	ffler.		220.00	180.00
	To check wiring functions.	-01	\$	120.00 28,789.48	\$ 100.00

**Note:** The repairer has agreed to undertake the repairs at our adjusted amount of \$16,100.00 lump sum corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be NINE ( 9 ) days.

Pursuant to your instruction we have **not** authorised repairs on your behalf.

PRESTICE APPRAISER SERVICES

LOUIS S C NG CAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer