



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2200768

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 14/02/2022
Reference CC3/CTI20011099/Kpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 9945Z
Insured Veh. SMD 8346A
Claim No. SNM20D203847/C02
Policy No. DMHCSNA00001942000
Accident Date 11/10/2020
Inspection Date 13/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI20011099/Kpa3q2 Date: 14/02/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMD 8346A	Veh. Inspected	SHD 9945Z
	Policy No.	DMHCSNA00001942000	Coverage (\$)	0.00
	Claim No.	SNM20D203847/C02	Excess (\$)	0.00
	Assign From		Assign Date	13/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	RENAULT LATITUDE (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	VF1ABL15AUC277909	Colour	METALLIC WHITE / RED
	Odometer	785312 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	SAILUN	9 mm
	L/H Front Tyre	215/60 R16	SAILUN	9 mm
	R/H Rear Tyre	215/60 R16	SAILUN	9 mm
	L/H Rear Tyre	215/60 R16	SAILUN	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/10/2020	Inspection Date	13/10/2020
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9945Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT	BENT / CRACKED	747.20	747.20
1	BUMPER BEAM FRT	BENT	663.70	663.70
1	BUMPER SPOILER FRT	DISTORTED	344.70	344.70
1	BUMPER ABSORBER FRT	CRACKED	394.68	394.68
1	BUMPER BRACKET FRT LH (HEADLAMP LOWER)	CRACKED	116.47	116.47
1	BUMPER BRACKET FRT RH (HEADLAMP LOWER)	SERVICEABLE	116.47	-
1	BUMPER RETAINER FRT LH	CRACKED	101.40	101.40
1	BUMPER RETAINER FRT RH	SERVICEABLE	101.40	-
1	BUMPER SUPPORT FRT	SERVICEABLE	10.70	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	147.00	-
1	BUMPER FOG LAMP GRILLE LH	CRACKED	207.21	207.21
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	152.80	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	237.40	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	237.40	-
1	HEADLAMP LH	BROKEN	743.60	743.60
1	HEADLAMP RH	MTG CRACKED	743.60	743.60
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	128.30	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	128.30	-
1	RADIATOR GRILLE FRAME	CRACKED	686.00	686.00
1	FRAME FULL SUPPORT PANEL	CRACKED	592.70	592.70
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	41.60	-
1	RADIATOR GRILLE	MTG CRACKED	969.90	969.90
1	RADIATOR GRILLE BADGE "RENAULT"	NECESSARY	225.36	225.36
1	DOOR MIRROR ASSY LH (CRACKED)	NOT CONSISTENT WITH THE IMPACT	1,483.40	-
1	FENDER PANEL FRT LH	BENT	437.10	437.10

Report Ref No. CC3/CTI20011099/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	437.10	-
1	WHEELARCH FRT LH	CRACKED	191.40	191.40
1	BUMPER UNDERTRAY FRT	CRACKED	292.50	292.50
1	SUBFRAME OUTER FRT	SERVICEABLE	1,094.20	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	AIR CLEANER HOSE	SERVICEABLE	175.85	-
1	AIR CLEANER LOWER	CRACKED	271.26	271.26
1	STEERING PUMP ELECTRIC	DISTORTED / CRACKED	2,026.70	2,026.70
1	AUTO COMPUTER	SERVICEABLE	1,287.30	-
1	SUBFRAME OUTER FRT	SERVICEABLE	1,094.20	-
	LESS 10% DISCOUNT		-1,730.03	-975.55
			15,570.28	8,779.93
	<u>SPECIAL NETT ITEMS</u>			
1	SET BUMPER CLIP FRT (SN)	NECESSARY	90.00	66.00
1	BUMPER BRACKET CLIP FRT (SN)	NOT NECESSARY	75.00	-
1	BUMPER SUPPORT CLIP FRT (SN)	NOT NECESSARY	10.00	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	55.00	-
1	SET RADIATOR GRILLE FRAME CLIP L70Y (SN)	NOT NECESSARY	60.00	-
1	SET BUMPER RETAINER CLIP FRT (SN)	NOT NECESSARY	70.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	70.00	-
1	BUMPER FOG LAMP GRILLE CLIP (SN)	NOT NECESSARY	65.00	-
1	BUMPER SPOILER CLIP (SN)	NOT NECESSARY	60.00	-
1	SET WHEELARCH CLIP FRT (SN)	NECESSARY	80.00	80.00
1	LICENCE PLATE HOLDER (SN)	SERVICEABLE	80.00	-
			715.00	146.00
	<u>LABOUR</u>			
	TOWING FEE.		170.00	50.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-

Report Ref No. CC3/CTI20011099/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BONNET LOCK,BONNET HINGE LH,BONNET HINGE RH,HEADLAMP PANEL FRT LH,HEADLAMP PANEL FRT RH,FRAME FULL SUPPORT BRACKET AND FENDER PANEL FRT RH.		1,800.00	500.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		250.00	30.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT BATTERY,ELECTRICAL WIRING FUSE BOX AND RELAY TO ENABLE REPAIR.	NOT NECESSARY	450.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,800.00	660.00
			5,790.00	1,260.00
GRAND TOTAL			22,075.28	10,185.93

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,550.00
---	--	--	--	-----------------

Report Ref No. CC3/CTI20011099/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 9945Z

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 9945Z

RE-INSPECTION

