

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8926R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BROKEN	1,106.00	1,106.00
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER SIDE BRACKET - RH	NOT NECESSARY	35.60	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
1	REAR BUMPER REINFORCEMENT BRACKET RH	NOT NECESSARY	80.30	-
1	REAR BUMPER UNDERCOVER	сит	228.00	228.00
1	REAR BUMPER REFLECTOR - RH	NOT NECESSARY	32.00	-
	LESS 20% DISCOUNT		-386.46	-271.20
			1,545.84	1,084.80
	SPECIAL NETT ITEMS			
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
			185.70	185.70
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	280.00
	SPRAY PAINTING CHARGE.		300.00	200.00
	WIRING CHARGE.		50.00	30.00
	REMOVE / REFIX REVERSE SENSOR.		100.00	30.00
	TOWING FEE.		60.00	
			910.00	540.00
	GRAND TOTAL		2,641.54	1,810.50

RECOMMENDED COST OF LUMP SUM REPAIRS	1,450.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC20011102/Eqf3e2

**CHEN TSUE YEE** 

**Automotive Assessor** 

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser