

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011104/UQD3E2

Date: 30/11/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN19336419000

Claimant Vehicle No : SMH6447J

Insured Vehicle No : XD8678L

Date of Loss: 10/10/2020

Nature of Claim: TP

Claim No: SNM20D203836/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH6447J**

Make & Model: HONDA FREED HYBRID, 1.5 (A)

Engine No: LEB5603544

Reg. Date: 29/01/2019 (Man. Year: 2018)

Chassis No: GB71069680

Colour: Grey

Odometer: 0 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	82,900.40	15,898.16	67,002.24	80.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,100.00	4,900.00	14,200.00	74.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	102,000.40	20,798.16	81,202.24	79.61
Approved Total (Overridden) (S\$)		16,600.00		
(S\$)	102,000.40	16,600.00	85,400.40	83.73
+ GST 7.00/7.00% (S\$)	7,140.03	1,162.00	5,978.03	83.73
Nett Amount (S\$)	109,140.43	17,762.00	91,378.43	83.73

INSPECTION

Date of Assignment: 14/10/2020

Date Inspected: 14/10/2020 Inspected At:

AP Automotive Services Pte Ltd (HQ)
Blk 9006 Tampines Street 93, #01-202
Singapore 528840

Estimated Period of Repair: 20.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2020)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH6447J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ROOF PANEL	Badly Dented / Buckled	4,681.00 FL	*2,045.00 FL
2	1		*ROOF PANEL GARNISH L+R	N/S Cracked	796.00 FL	*66.50 FL
3	1		*ROOF TRIM	Warped	3,317.00 FL	*1,250.00 FL
4	1		*SET ROOF TRIM CLIPS	Necessary	250.00 FL	*60.00 FL
5	1		*REAR WINDSCREEN	Shorted	1,255.00 FL	*1,064.70 FL
6	1		*REAR WINDSCREEN MOULDING	Necessary	371.00 FL	*54.60 FL
7	2		*REAR WINDSCREEN HEAT STRIP L+R	Not Necessary	682.00 FL	*- FL
8	1		*REAR TAILGATE	Badly Dented	2,170.00 FL	*1,044.40 FL
9	1		*REAR TAILGATE SPOILER	Cracked	1,365.00 FL	*680.00 FL
10	1		*REAR TAILGATE SPOILER LAMP	Cracked	396.00 FL	*234.00 FL
11	1		*REAR TAILGATE LOGO - HONDA	Necessary	105.00 FL	*38.00 FL
12	1		*REAR TAILGATE EMBLEM - FREED	Necessary	110.00 FL	*56.00 FL
13	1		*REAR TAILGATE EMBLEM - HYBRID	Necessary	108.00 FL	*60.00 FL
14	1		*REAR TAILGATE CHROME HANDLE	Bent	498.00 FL	*315.00 FL
15	1		*REAR TAILGATE HANDLE OPENER	Not Necessary	289.00 FL	*- FL
16	2		*REAR TAILGATE VRN LAMP L+R	Not Necessary	140.00 FL	*- FL
17	2		*REAR TAILGATE LAMP L+R	N/S Broken / O/S Cracked	1,066.00 FL	*735.20 FL
18	1		*REAR TAILGATE LOCK	Twisted / Jammed	312.00 FL	*145.00 FL
19	1		*REAR TAILGATE LOCK CATCH	Not Necessary	125.00 FL	*- FL
20	1		*REAR TAILGATE INNER TRIM	Distorted	589.00 FL	*485.20 FL
21	1		*REAR TAILGATE INNER TRIM TOP L+R	N/S Deformed	680.00 FL	*105.00 FL
22	1		*REAR TAILGATE INNER TRIM TOP CENTER	Not Necessary	340.00 FL	*- FL
23	1		*REAR TAILGATE INNER TRIM CLIPS (30PCS)	Not Necessary	360.00 FL	*- FL
24	2		*REAR TAILGATE HINGE L+R	Not Necessary	420.00 FL	*- FL
25	1		*REAR TAILGATE DAMPER L+R	N/S Twisted	698.00 FL	*225.00 FL
26	2		*REAR TAILGATE STOPPER L+R	Necessary	48.00 FL	*30.00 FL
27	1		*REAR TAILGATE INNER HANDLE	Not Necessary	92.00 FL	*- FL
28	1		*REAR TAILGATE WEATHERSTRIP	Twisted	385.00 FL	*285.00 FL
29	2		*TAILLAMP L+R	N/S Broken / O/S Cracked	1,790.00 FL	*1,323.20 FL
30	2		*TAILLAMP SEAL L+R	Not Necessary	310.00 FL	*- FL
31	4		*TAILLAMP CLIP L+R	Not Necessary	50.00 FL	*- FL
32	1		*TAILLAMP PANEL L+R	N/S Dented	980.00 FL	*269.00 FL
33	1		*REAR BUMPER	Distorted	1,560.00 FL	*828.90 FL
34	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FL	*50.00 FL
35	1		*REAR BUMPER REFLECTOR L+R	N/S Cracked	360.00 FL	*85.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR BUMPER REVERSE SENSOR	Shorted	860.00 FS	*200.00 FS
37	1		*REAR BUMPER RETAINER L+R	N/S Bent	368.00 FL	*45.50 FL
38	1		*REAR BUMPER REINFORCEMENT BAR	No such part	820.00 FL	*- FL
39	2		*REAR BUMPER BRACKET	No such part	428.00 FL	*- FL
40	1		*REAR BUMPER SPONGE	No such part	370.00 FL	*- FL
41	1		*REAR FENDER L+R	N/S Buckled / O/S Repair	5,780.00 FL	*981.20 FL
42	1		*REAR FENDER INNER PANEL L+R	N/S Dented	5,260.00 FL	*1,150.00 FL
43	2		*REAR FENDER WINDOW L+R	Not Necessary	1,968.00 FL	*- FL
44	1		*REAR FENDER WINDOW MOULDING L+R	N/S Necessary	668.00 FL	*85.00 FL
45	1		*REAR FENDER TOP INNER TRIM L+R	N/S Deformed	886.00 FL	*243.00 FL
46	1		*REAR FENDER CENTER INNER TRIM L+R	N/S Distorted	1,060.00 FL	*424.10 FL
47	2		*REAR FENDER LOWER INNER TRIM L+R	No such part	1,848.00 FL	*- FL
48	1		*REAR FENDER INNER TRIM CLIPS (40PCS)	Not Necessary	480.00 FL	*- FL
49	2		*REAR FENDER DOOR TRACK L+R	Not Necessary	900.00 FL	*- FL
50	2		*REAR FENDER DOOR TRACK END L+R	Not Necessary	420.00 FL	*- FL
51	1		*REAR FENDER PETROL COVER LH	Warped	598.00 FL	*122.80 FL
52	1		*REAR FENDER COWLING L+R	N/S Torn	478.00 FL	*135.20 FL
53	1		*SET REAR FENDER COWLING CLIPS	Necessary	220.00 FL	*50.00 FL
54	1		*REAR END PANEL	Badly Dented	1,089.00 FL	*507.20 FL
55	1		*REAR END PANEL TOP GARNISH	Twisted	574.00 FL	*185.20 FL
56	10		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	120.00 FL	*- FL
57	1		*REAR END PANEL INNER PANEL	Repair	1,190.00 FL	*- FL
58	2		*REAR END PANEL QUARTER PANEL L+R	No such part	1,280.00 FL	*- FL
59	1		*REAR FLOOR PANEL	Repair	1,578.00 FL	*- FL
60	1		*REAR FLOOR PANEL TOP BOARD	Distorted	696.00 FL	*588.20 FL
61	2		*REAR FLOOR PANEL ACCESSORY FOAM L+R	No such part	510.00 FL	*- FL
62	1		*REAR BATTERY PACK (NPA)	Not Necessary	0.00 FL	*- FL
63	2		*REAR CHASSIS L+R (NPA)	Repair	0.00 FL	*- FL
64	2		*REAR CHASSIS EXTENSION L+R	Not Necessary	1,788.00 FL	*- FL
65	1		*REAR EXHAUST	Not Necessary	970.00 FL	*- FL
66	1		*REAR EXHAUST MOUNTING	Not Necessary	320.00 FL	*- FL
67	2		*REAR EXHAUST GASKET L+R	Not Necessary	210.00 FL	*- FL
68	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	390.00 FL	*- FL
69	1		*REAR DOOR LH	Warped	2,188.00 FL	*988.20 FL
70	1		*REAR DOOR HANDLE LH	Not Necessary	298.00 FL	*- FL
71	1		*REAR DOOR HANDLE END CAP LH	Not Necessary	120.00 FL	*- FL
72	1		*REAR DOOR LOWER PROTECTOR STRIP LH	Not Necessary	228.00 FL	*- FL
73	1		*REAR DOOR WINDOW MOULDING LH	Not Necessary	215.00 FL	*- FL
74	1		*REAR DOOR WINDOW INNER MOULDING LH	Not Necessary	215.00 FL	*- FL
75	1		*REAR DOOR WINDOW STICKER LH	Necessary	198.00 FL	*80.00 FL
76	1		*REAR DOOR LOCK LH	Not Necessary	642.00 FL	*- FL
77	1		*REAR DOOR LOCK CATCH LH	Not Necessary	105.00 FL	*- FL
78	1		*REAR DOOR INNER TRIM LH	Not Necessary	968.00 FL	*- FL
79	10		*REAR DOOR INNER TRIM CLIPS	Not Necessary	120.00 FL	*- FL
80	1		*REAR DOOR INNER HANDLE LH	Not Necessary	420.00 FL	*- FL
81	1		*REAR DOOR WINDOW REGULATOR LH	Not Necessary	558.00 FL	*- FL
82	1		*REAR DOOR POWER WINDOW MOTOR LH	Not Necessary	798.00 FL	*- FL
83	1		*REAR DOOR HINGE TOP LH	Not Necessary	390.00 FL	*- FL
84	1		*REAR DOOR HINGE CENTER LH	Not Necessary	390.00 FL	*- FL
85	1		*REAR DOOR HINGE BOTTOM LH	Not Necessary	390.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
86	1		*REAR DOOR TRACK WHEEL TOP LH	Not Necessary	758.00 FL	*- FL
87	1		*REAR DOOR TRACK WHEEL CENTER LH	Not Necessary	758.00 FL	*- FL
88	1		*REAR DOOR TRACK WHEEL BOTTOM LH	Not Necessary	758.00 FL	*- FL
89	1		*REAR DOOR AUTO DOOR POWER MOTOR LH	Shorted	2,472.00 FL	*1,617.00 FL
90	2		*SET REAR DOOR STOPPER	Not Necessary	110.00 FL	*- FL
91	1		*REAR DOOR WEATHERSTRIP LH	Necessary	412.00 FL	*185.40 FL
92	1		*REAR DOOR WEATHERSTRIP INNER LH	Not Necessary	425.00 FL	*- FL
93	1		*REAR PASSENGER SEAT SECOND ROW LH	Not Necessary	1,550.00 FL	*- FL
94	1		*REAR PASSENGER SEAT SECOND ROW RH	Not Necessary	2,980.00 FL	*- FL
95	2		*REAR PASSENGER SEAT SECOND ROW SEATBELT L+R	Not Necessary	2,462.00 FL	*- FL
96	1		*REAR PASSENGER SEAT SECOND ROW SEATBELT CENTER	Not Necessary	1,231.00 FL	*- FL
97	1		*REAR PASSENGER SEAT THIRD ROW LH	Not Necessary	1,550.00 FL	*- FL
98	1		*REAR PASSENGER SEAT THIRD ROW RH	Not Necessary	2,980.00 FL	*- FL
99	2		*REAR PASSENGER SEAT THIRD ROW SEATBELT L+R	Not Necessary	2,462.00 FL	*- FL
100	1		*REAR PASSENGER SEAT THIRD ROW SEATBELT CENTER	Not Necessary	1,231.00 FL	*- FL
101	1		*REAR ABSORBER LH	Not Necessary	812.00 FL	*- FL
102	1		*REAR LOWER ARM LH	Not Necessary	858.00 FL	*- FL
103	1		*REAR KNUCKLE ARM LH	Not Necessary	840.00 FL	*- FL
104	1		*REAR KNUCKLE BEARING LH	Not Necessary	676.00 FL	*- FL
105	1		*REAR KNUCKLE BEARING HUB LH	Not Necessary	485.00 FL	*- FL
106	1		*REAR AXLE	Not Necessary	3,120.00 FL	*- FL
107	1		*ROOF PANAL SEALANT	Necessary	150.00 FS	*50.00 FS
108	1		*REAR WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
109	1		*REAR LICENCE PLATE	Bent	50.00 FS	*40.00 FS
110	1		*REVERSE CAMERA	Shorted	600.00 FS	*300.00 FS
111	2		*TAILLAMP PANEL SEALANT	Not Necessary	240.00 FS	*- FS
112	2		*REAR FENDER SEALANT L+R	Not Necessary	240.00 FS	*- FS
113	2		*REAR FENDER INNER PANEL SEALANT L+R	Not Necessary	240.00 FS	*- FS
114	1		*REAR FENDER WINDOW SEALANT	N/S Necessary	240.00 FS	*30.00 FS
115	2		*REAR DOOR VISOR	Necessary	180.00 FS	*50.00 FS
116	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*50.00 FS
117	2		*REAR END PANEL QUARTER PANEL SEALANT	Not Necessary	240.00 FS	*- FS
118	1		*REAR FLOOR PANEL SEALANT	Not Necessary	200.00 FS	*- FS
119	2		*REAR TYRE	Not Necessary	1,600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 102,348.00 19,682.70
- List Item Discount on L Items 20.00/20.00% (S\$) 19,447.60 3,784.54

Total Parts (S\$) 82,900.40 15,898.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON AFFECTED AREAS	New	5,100.00	1,600.00
2	PANEL BEATING ON AFFECTED AREAS	New	7,200.00	2,500.00
3	TO RNR REAR EXHAUST	New	250.00	0.00
4	TO RNR ROOF TRIM	New	500.00	120.00
5	TO CHECK WIRING AND TAILLAMP FUNCTION }	New	150.00	30.00
6	TO CHECK WIRING AND TAILGATE LAMP FUNCTION }	New	150.00	0.00
7	TO UNLOAD AND UPHOLSTERY REAR BOOT	New	400.00	100.00
8	TO CHECK WATER LEAK	New	100.00	0.00
9	TO RNR REAR DOOR MECHANISM	New	300.00	60.00
10	TO RNR REAR DOOR WHEEL	New	250.00	0.00
11	TO RNR REAR PASSENGER SEAT SECOND ROW	New	400.00	0.00
12	TO RNR REAR PASSENGER SEAT THIRD ROW	New	400.00	0.00
13	TO RNR REAR PASSENGER SEATBELT SECOND ROW	New	300.00	0.00
14	TO RNR REAR PASSENGER SEATBELT THIRD ROW	New	300.00	0.00
15	TO RNR REAR BATTERY PACK	New	600.00	0.00
16	TO RNR FUEL TANK	New	250.00	60.00
17	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	50.00
18	TO RNR REAR TAILGATE MECHANISM	New	350.00	60.00
19	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	50.00
20	TO PERFORM RUST PROOFING	New	400.00	150.00
21	TO RNR REAR WINDSCREEN	New	350.00	120.00
22	TO RNR UNDERCARRIAGE	New	150.00	0.00
23	TO CHECK UNDERCARRIAGE ALIGNMENT	New	150.00	0.00
24	TO CHECK WHEEL BALANCING	New	150.00	0.00
25	TO VACUUM WINDOW GLASSES	New	150.00	0.00
Gross Labour Cost (\$\$)			19,100.00	4,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >