

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20011105/QEA3Q2
Date: 08/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100449769
Claimant Vehicle No :	SG6071T	Insured Vehicle No :	SGE3692Z
Date of Loss:	08/10/2020	Nature of Claim:	TP
		Claim No:	8852194659SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG6071T		
Make & Model:	MAN A95, 10.5 D (A)	Engine No:	50351900665185
Reg. Date:	14/01/2019 (Man. Year: 2018)	Chassis No:	WMAA95ZZXKF008635
Colour:	Multi-colour	Odometer:	201392 km
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	75.00	75.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,832.00	1,132.00	700.00	38.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,907.00	1,207.00	700.00	36.71
+ Loss of Use (2.5 x S\$350.00/day) (S\$)		875.00		

(S\$)	2,082.00
Liabile Amount (50.00%) (S\$)	1,041.00
+ Doc/Search Fee (S\$)	7.00
Nett Liability (S\$)	1,048.00

INSPECTION

Date of Assignment: 12/10/2020

Date Inspected: 12/10/2020

Estimated Period of Repair: 2.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*STICKER SMRT	Necessary	75.00 FS	*75.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					75.00	75.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR RH PORTION REAR TO CENTER	New	1,060.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	772.00	602.00
Gross Labour Cost (\$\$)			1,832.00	1,132.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >