



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 63K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BONNET LEADING SEAL	DEFORMED	87.00	87.00
2	FRONT BUMPER SIDE RETAINER RH / LH	NECESSARY	118.00	118.00
1	FRONT BUMPER INDICATOR LAMP RH	BROKEN	210.20	210.20
1	INTERCOOLER RH	SERVICEABLE	3,088.00	-
1	FRONT SUSPENSION LOWER CONTROL ARM	BENT	1,195.50	1,195.50
1	FRONT SUEPSNTION TOP ARM	BENT	561.70	561.70
1	FRONT WHEEL BEARING C/W HUB ASSY RH	DAMAGED	678.10	678.10
1	FRONT STABILISER LINK RH	BENT	74.10	74.10
1	FRONT STEERING KNUCKLE ARM	BENT	1,680.60	1,680.60
1	FRONT SHOCK ABSORBER RH	TO REPAIR SEE LABOUR	2,525.20	-
	LESS 10% DISCOUNT		-1,021.84	-460.52
			9,196.56	4,144.68
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT BONNET (SN)	CRACKED	11,000.00	6,800.00
1	RH HEAD LIGHT ASSY (SN)	CRACKED	4,500.00	3,300.00
1	FRONT BUMPER (SN)	TORN	8,000.00	6,500.00
1	FRONT BUMPER LOWER SPOILER (SN)	CRACKED	1,600.00	1,600.00
1	FRONT FENDER ASSY RH (SN)	CRACKED	4,200.00	3,200.00
1	FRONT SPORT RIM RH (SN)	DENTED	9,000.00	4,000.00
1	FRONT TYRE RH (SN)	SERVICEABLE	1,050.00	-
			39,350.00	25,400.00
<b><u>LABOUR</u></b>				
	TOWING FEE.		120.00	120.00
	TO CHECK WIRING.}		120.00	50.00
	TO INSTALL, ALIGN AND REFOCUS HEAD LIGHT BEAMS. }		8.00	-
	TO CONDUCT 4-WHEEL COMPUTERISED WHEEL ALIGNMENT TO ALIG WHEELS.		120.00	120.00
	TO REMOVE AND REPLACE DAMAGED FRONT RIGHT HAND UNDERCARRIAGE AND SUSPENSION PARTS.		1,500.00	220.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO PANEL BEATING AFFECTED AND DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT SHOCK ABSORBER RH.		1,500.00	600.00
	SPRAY PAINTING CHARGES TO PAINT THE FRONT BUMPER, FRONT SUPPORT PANEL AND AFFECTED AREAS.		900.00	600.00
			4,268.00	1,710.00
GRAND TOTAL			52,814.56	31,254.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				25,000.00

Report Ref No. CS3/EGI20001015/Usd3e2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.