

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20011109/AVF3E2

Date: 14/04/2021

REFERENCE

Insured/Claimant:	TANG SOO TECK	Policy No:	1700025408-03	
Date of Loss:	13/10/2020	Nature of Claim:	OD	Claim No: 0917224459SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ4048E		
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Engine No:	CHZ383462
Reg. Date:	08/07/2017 (Man. Year: 2017)	Chassis No:	WAUZZZ8V9H1078670
Colour:	Red	Odometer:	68638 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$82,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,554.00	12,714.24	8,839.76	41.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,512.00	7,732.00	4,780.00	38.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	34,066.00	20,446.24	13,619.76	39.98
+ GST 7.00/7.00% (S\$)	2,384.62	1,431.24	953.38	39.98
Nett Amount (S\$)	36,450.62	21,877.48	14,573.14	39.98

INSPECTION

Date of Assignment:	14/10/2020		
Date Inspected:	14/10/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	11.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	185.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	38.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Cracked	159.00 FS	*126.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	530.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LH / RH	N/S Deformed	586.00 FS	*234.40 FS
7	1		*FRONT BUMPER COVER TRIM - LH	Not Necessary	161.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
9	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	189.00 FS	*150.80 FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	186.00 FS	*148.40 FS
11	1		*FRONT REINFORCEMENT BEAM	Bent	715.00 FS	*571.60 FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	187.00 FS	*149.60 FS
13	1		*FOAM FILLER PIECE COVER	Cracked	121.00 FS	*96.40 FS
14	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
15	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
16	1		*SIGNAL HORN - LH HIGH TONE	Not Necessary	197.00 FS	*- FS
17	1		*FRONT FENDER - LH	Buckled	841.00 FS	*672.80 FS
18	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	71.00 FS	*- FS
19	1		*FRONT FENDER BRACKET - LH	Not Necessary	38.00 FS	*- FS
20	1		*FRONT FENDER BRACE	Not Necessary	95.00 FS	*- FS
21	1		*WHEEL HOUSING LINER - LH	Not Necessary	167.00 FS	*- FS
22	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	88.00 FS	*- FS
23	1		*BONNET	Dented	3,134.00 FS	*2,507.20 FS
24	1		*BONNET ATTACHMENT PARTS	Not Necessary	163.00 FS	*- FS
25	2		*BONNET LID HINGE - LH / RH	Not Necessary	122.00 FS	*- FS
26	1		*BONNET SAFETY CATCH	Not Necessary	89.00 FS	*- FS
27	2		*BONNET STRIKER - LH / RH	Not Necessary	218.00 FS	*- FS
28	1		*BONNET EDGE PROTECTION	Necessary	28.00 FS	*21.84 FS
29	1		*BONNET CATCH HOOK	Not Necessary	63.00 FS	*- FS
30	2		*BONNET LID LOCK	Not Necessary	423.00 FS	*- FS
31	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	57.00 FS	*- FS
32	1		*LED HEADLIGHT - LH	Cut	5,455.00 FS	*4,364.00 FS
33	1		*LIFT CYLINDER - LH	Not Necessary	141.00 FS	*- FS
34	1		*LIFT CYLINDER HOSE	Not Necessary	67.00 FS	*- FS
35	1		*RADIATOR AIR GUIDE - LH	Cracked	24.00 FS	*19.20 FS
36	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	12.00 FS	*- FS
37	1		*REAR BUMPER	Repair	1,944.00 FS	*- FS
38	1		*REAR BUMPER FIXING PARTS	Not Necessary	191.00 FS	*- FS
39	1		*REAR BUMPER SPOILER	Cut	234.00 FS	*187.20 FS
40	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
41	1		*SUNDRIES	Necessary	350.00 FS	*25.60 FS
42	1		*LOCK CARRIER (Supplementary)	Cracked	719.00 FS	*575.20 FS
43	1		*COOLANT (Supplementary)	Necessary	91.00 FS	*72.32 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 21,554.00 12,714.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,500.00
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND HINGES	New	3,000.00	1,650.00
5	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
6	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
7	TO TOW VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
9	TO RESPRAY REAR BUMPER	New	900.00	550.00
10	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. (Supplementary)	New	1,200.00	1,200.00
11	TO RENEW LOCK CARRIER AND ALIGN TO POSITION. (Supplementary)	New	2,100.00	1,250.00
Gross Labour Cost (\$\$)			12,512.00	7,732.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >