

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20011111/AQF3Q2

Date: 15/03/2021

REFERENCE

Insured/Claimant: CHONG MINGYANG(ZHANG MINGYANG) Policy No: 1800116197-01

Date of Loss: 07/10/2020

Nature of Claim: OD

Claim No: 5639569670SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME3816M		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI COD S-TRONIC (A)	Engine No:	CZE693571
Reg. Date:	27/09/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8VXJ1078294
Colour:	Blue	Odometer:	26996 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$88,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,021.00	6,102.00	5,919.00	49.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,922.00	1,492.00	1,430.00	48.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,943.00	7,594.00	7,349.00	49.18
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	14,343.00	6,994.00	7,349.00	51.24
+ GST 7.00/7.00% (S\$)	1,004.01	489.58	514.43	51.24
Nett Amount (S\$)	15,347.01	7,483.58	7,863.43	51.24

INSPECTION

Date of Assignment: 14/10/2020

Date Inspected: 14/10/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	185.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	530.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	159.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	293.00 FS	*- FS
6	1		*FRONT BUMPER COVER TRIM - RH	Not Necessary	161.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	1,406.00 FS	*- FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	189.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	186.00 FS	*148.40 FS
10	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
11	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
12	1		*FRONT REINFORCEMENT BEAM	Not Necessary	715.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	187.00 FS	*- FS
14	1		*FOAM FILLER PIECE COVER	Not Necessary	121.00 FS	*- FS
15	1		*LED HEADLIGHT - RH	Cut	5,455.00 FS	*4,364.00 FS
16	1		*LIFT CYLINDER - RH	Not Necessary	141.00 FS	*- FS
17	1		*RADIATOR AIR GUIDE - RH	Not Necessary	24.00 FS	*- FS
18	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
19	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 12,021.00 6,102.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY.	New	280.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,000.00	500.00
4	TO RESPRAY FRONT BUMPER.	New	1,100.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			2,922.00	1,492.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >