Adjuster Report Page 1 of 3

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20011121/R1SD3E2

**Date:** 17/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993925

Claimant Vehicle No: SLV4433A Insured Vehicle No: SLE1672K

Date of Loss: 03/10/2020 Nature of Claim: TP Claim No: 0923102186SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLV4433A

Make & Model: MAZDA 3, 1.5 SEDAN AT EU6 (A) Engine No: P520451285

Reg. Date: 29/12/2017 (Man. Year: 2017) Chassis No: JM6BN22A8H0158645

Colour: Blue Odometer: 56012 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment: 13/10/2020

Date Inspected: 19/10/2020 Inspected At: Mk9 Super Speed (HQ)

7 SOON LEE STREET# 05-32 ISPACE

Singapore 627608

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

# **REPAIR DETAILS**

# **Recommended Parts**

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*REAR BUMPER	Repair	0.00 F	*-F
F=Franchise part.		Total Parts (S\$)	0.00	0.00
	Report was u	nsubmitted during this print-out.		

Adjuster Report Page 3 of 3

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >