



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Teo Beng Hua Reg No/Reg Date SLX3540U / 26/03/201 Date In/Mileage / 0 Chassis No GF7W0401075 Engine No 4J11XK9004 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE Colour/Trim COO QUARTZ BROWN ME/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	14/10/2020/ 14:17	TLC	442 / CocoLu	58424		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000				450			1800 3300.00
RENEW REAR BUMPER, TAILGATE, REAR END PANEL, REPAIR REAR FENDER LH REAR COMPARTMENT,							60 100.00
E PNT88000							160 400.00
REMOVE INSTALL PARKING SENSOR							240 300.00
E PNT88000							✓ 80.00
REMOVE & INSTALL REAR COMPARTMENT TRIMS AND SEATS							new 40.00
E PNT88000							1225 2520.00
REMOVE & INSTALL REAR TAILGATE GLASS							X 150.00
M SUNDRY							20 30.00
APPLY SEALANT FOR TAILGATE GLASS							120 200.00
M SUNDRY							48 80.00
C&C LOGO							new 220.00
E PNT98000							X 50.00
SPRAY PAINT FOR REAR BUMPER, TAILGATE, REAR END PANEL REAR COMPARTMENT, REAR FENDER LH,							X 60.00
E PNT88000							X 30.00
REMOVE & INSTALL TAILGATE TRIMS							
A 54900099							
CHECK WIRING & ELECTRICAL SYSTEM							
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							
M SUNDRY							
APPLY SEALANT FOR ACCIDENT PORTION							
M SUNDRY							
SUPPLY PARKING SENSOR							
M SUNDRY							
SUPPLY STICKERS							
M SUNDRY							
SUPPLY REAR BUMPER TOP COVER							
M SUNDRY							
SUPPLY REAR FOG LAMP COVER							


Estimate

Confirm & accepted by

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Teo Beng Hua Reg No/Reg Date SLX3540U / 26/03/201 Date In/Mileage / 0 Chassis No GF7W0401075 Engine No 4J11XK9004 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE Colour/Trim COO QUARTZ BROWN ME/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	14/10/2020/ 14:17	TLC	442 / CocoLu	58424			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								X 900.00
RENEW & SUPPLY AUTO TAILGATE SYSTEM								20. 40.00
M SUNDRY								
Sundry								
M	REINFORCEMENT,RR BUMPER,LH			1.00	79.00	23.00	? 60.83	
M	REINFORCEMENT,RR BUMPER,RH			1.00	79.00	23.00	? 60.83	
M	BRKT,R/BMPR FACE SIDE,RH			1.00	12.00	23.00	X 9.24	
M	BRKT,R/BMPR FACE SIDE,LH			1.00	12.00	23.00	? 9.24	
M	FACE,RR BUMPER			1.00	807.00	23.00	de✓ 621.39	
M	EXTENSION,RR BUMPER			1.00	232.00	23.00	de✓ 178.64	
M	MOULDING,RR BUMPER,LH			1.00	106.00	23.00	? 81.62	
M	MOULDING,RR WHEEL ARCH,LH			1.00	199.00	23.00	? 153.23	
M	MOULDING,RR BUMPER,RH			1.00	106.00	23.00	? 81.62	
M	PANEL,RR END			1.00	324.00	23.00	bt✓ 249.48	
M	PANEL,RR END,INR LH			1.00	146.00	23.00	? 112.42	
M	PANEL,RR END,INR RH			1.00	146.00	23.00	? 112.42	
M	SHIELD,RR WHEEL,RR LH			1.00	22.00	23.00	X 16.94	
M	SHIELD,RR WHEEL,FR LH			1.00	0.00	23.00		
M	PANEL ASSY,TAILGATE			1.00	984.00	23.00	bt✓ 757.68	
M	W/STRIP,TAILGATE OPENING			1.00	213.00	23.00	ant✓ 164.01	
M	GARNISH,TAILGATE			1.00	494.00	23.00	X 380.38	
M	DAM,TAILGATE,LWR			1.00	41.00	23.00	nei✓ 31.57	
M	STOPPER,WINDSHIELD GLASS			2.00	3.00	23.00	nei✓ 4.62	
M	DAM,TAILGATE SIDE			2.00	27.00	23.00	nei✓ 41.58	
M	FASTENER,WINDSHIELD			4.00	6.00	23.00	nei✓ 18.48	
M	DAM,TAILGATE,UPR			1.00	13.00	23.00	nei✓ 10.01	
M	LATCH,TAILGATE			1.00	383.00	23.00	bt✓ 294.91	
M	TRIM,TAILGATE			1.00	329.00	23.00	? 253.33	
M	MARK,OUTLANDER			1.00	95.00	23.00	nei✓ 73.15	
M	TRIM,RR END			1.00	123.00	23.00	de✓ 94.71	
M	BOX,CARGO FLOOR			1.00	204.00	23.00	de✓ 157.08	
M	LAMP ASSY,COMB,RR LH			1.00	600.00	23.00	? 462.00	
M	LAMP ASSY,COMB,RR RH			1.00	600.00	23.00	X 462.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of the rubber seal or other repair requiring the removal of the windscreen.